

Village of New Denver Bosun Hall Building Assessment



Prepared By:

9dot Engineering Inc.

Suite 304, 625 Front Street Nelson, BC, V1L 4B6

www.9doteng.com

December 6,

2016

Revision: 1.3

Project Number: 16-013

Prepared for: Village of New Denver

© 9dot Engineering Inc., 2016

ALL RIGHTS RESERVED. This report is copyrighted and contains proprietary and privileged technical information that is the intellectual property of 9dot Engineering Inc. and AquaDiversities Inc. Any unauthorized reprint or use of this material is prohibited.

Article I. Table of Contents

1. Introduction.....	3
1.a.Overview.....	3
1.b.Previous Work and Documentation.....	5
1.c. Heritage Status.....	6
1.d.Building Bylaws	6
2. Building Assessment	6
2.a.Site Analysis, Lot Grading, Drainage	7
2.b.Structure	7
2.c. Foundation.....	8
2.d.Basement and Crawl Space.....	10
2.e.Building Envelope.....	11
2.e.i. Roof	12
2.e.ii. Eaves Troughs	14
2.e.iii. Exterior Walls	14
2.e.iv. Windows	16
2.e.v. Doors.....	16
2.e.vi. Foundation.....	16
2.f. Moisture Concerns	16
2.g.Porches, Decks and Balconies	17
2.h.Interior Walls, Ceilings and Floors	19
2.i. Attic, Ventilation and Insulation	20
2.i.i. Overview.....	20
2.i.ii. Ventilation.....	21
2.i.iii. Insulation.....	21
2.j. Kitchen and Bathrooms	22
2.k.Heating and Cooling Systems.....	22
2.l. Electrical System	23
2.m.Plumbing System.....	23
3. Proposed Renovations	25
4. Recommendations	26
5. Conclusion	26
Appendix A – Drawings.....	27
Appendix B – Renovation Plan Budget	28
Appendix C – Fire Safety Inspection Form	29
Appendix D – Assured Home Inspection Ltd. Building Inspection (2016).....	30

Article II. Table of Figures

Figure 1 - Bosun Hall from Bellevue St.	5
Figure 2 - Site Grading East of Building.....	7
Figure 3 - No Ledger Board @ Kitchen Rafters	8
Figure 4 - PTW Foundation Rot Prevalent Around Entire Building	9
Figure 5 - North East Corner Sill Plate (Dry Rot)	9
Figure 6 - Sloping Hall Floor	10
Figure 7 – Moisture Damage in Crawlspace and Electrical	11
Figure 8 - Crawlspace Vent	11
Figure 9 - Flashing at New Building Facade Installed Incorrectly.....	12
Figure 10 - Metal Roofing	13
Figure 11 - MBR Roofing	13
Figure 12 - Stucco Over Original Wood Siding	14
Figure 13 - Hardie Plank Siding Separating @ Joints	15
Figure 14 - West Facing Windows	16
Figure 15 - Front Balcony.....	17
Figure 16 - Side Deck	17
Figure 17 - Dry Rot @ Balcony Post	18
Figure 18 - Balcony Guardrail	18
Figure 19 - Mezzanine	19
Figure 20 - Dry Moisture Stain on Ceiling	19
Figure 21 - Stairway to Mezzanine	20
Figure 22 - Ant Colony in Attic.....	21
Figure 23 - Attic Gable Vent.....	21
Figure 24 - Insulation Covering Overhangs in Main Hall Roof	22

1. Introduction

Bosun Hall serves as a community building in the Village of New Denver (The Village), and is a well-known historical landmark in the area. It is currently occupied, and houses large community functions and events such as dances, bingos, movie screenings, holiday celebrations and activities, weddings, public meetings, and conferences. Bosun Hall is managed by Lucerne Association for Community Education (LACE) on behalf of the village.

The purpose of this report is to assess the current condition of Bosun Hall, owned by the Village of New Denver. This report will help to inform how funds should be allocated towards ensuring continued use of the building by the community and was not prompted by a destructive event such as a flood, fire, earthquake or vehicle impact. As such, this assessment covers the overall condition of the accessible and/or visible components of the building during the site visit and study period.

1.a. Overview

The building has a capacity of 275 people (0.75 m² per person), 217 in the main hall and 58 in the stage area, with three points of exit from the main floor, according to May 2015 drawings provided by the Village. Overall the building is in poor condition with several issues that will require major renovations and repairs in order to ensure service to the community for many years to come.

Overall, Bosun Hall exhibits serious structural and foundation issues (including site grading and drainage) that need to be addressed prior to pursuing any renovations to improve the functionality and aesthetics of the building. The roof trusses, roofing material, and the foundation requires replacement as outlined in this report.

Several other minor renovations and repairs are recommended to improve the building and ensure that it continues to be usable in future years. The renovation 'wish list' provided by the Village of New Denver has been included for record keeping purposes and Class C unit price estimates have been included for options to help direct future planning and financing. The next step that the Village of New Denver is recommended to take in order to address the recommendations in this report will be sending out a tender for pricing on the scope of work desired in order to confirm the suggested budget. Once the budget has been confirmed, the Village should consult with any authorities having jurisdiction (eg. building inspector) as needed, before proceeding with major renovations.

Drawings provided by 9dot Engineering Inc. can be found in **Appendix A**.

9dot Engineering Inc. (9dot) recommends further consultation from professionals for review of building components outside the scope of this report, as listed below (Details can be found in Section 2.k, 2.m and Section 3):

- Existing septic system review including design capacity, location and assessment of septic field; and,
- Old fuel line coming through stucco @ East exterior wall (possible buried oil tank).

Overall, major renovations are anticipated to cost \$547,500.

Minor renovations and additional work (including maintenance upgrades, minor repairs and further consultation) can be expected to add approximately \$150,000.

Several other minor renovations and repairs are recommended to improve the building and ensure that it continues to be usable in future years. The renovation 'wish list' provided by the Village of New Denver has been included for record keeping purposes and very rough unit price estimates have been included for options to help direct future planning and financing. In total, the renovation 'wish list' is estimated to cost approximately \$275,000.

A detailed breakdown of these estimates can be found in **Appendix B**.

**** All budgetary estimates provided in this report are Class C estimates as defined below:**

"Class C estimate (±25-40%): An estimate prepared with limited site information and based on probable conditions affecting the project. It represents the summation of all identifiable project elemental costs and is used for program planning, to establish a more specific definition of client needs and to obtain preliminary project approval." (APEG BC, Budget Guidelines for Consulting Engineering Services, 2009)

**** All totals do not include applicable taxes.**

1.b. Previous Work and Documentation

Bosun Hall, at 710 Bellevue St. in New Denver, BC was built by J.C. Harris in 1898 (Figure 1). At that time it was constructed as an opera house intended to accommodate travelling entertainers and local talent in all forms of art including drama, music, poetry and literature.



Figure 1 - Bosun Hall from Bellevue St.

Bosun Hall underwent significant renovations in 1995, following a study on the structural integrity of the building by Daniel Pasemko. The renovations included replacement of the section of floor and substructure/foundation in the main hall, and removal of dry rot from walls. Over subsequent years, other sections of the building were repaired and replaced as needed to maintain the building. Because of all these renovations, very little of the original structure and architecture remain.

In 2010 a new front façade was put on the building (Figure 1). This work also prompted a building inspection by Lynch Building Inspection Services on the stability of the roof, which recommended the replacement of the roof of the building immediately.

In 2012, Steven Thomson, P.Eng. of 9dot Engineering Inc. developed a Project Plan which was based on previous reports and used for grant applications to help bring the building into compliance with the BC Building Code. It addressed major issues including energy efficiency, asbestos risks, and structural improvements to the hall roof. The Project Plan also included a budget for a grid tied solar energy system. This work has not yet been undertaken due to lack of grant funding.

1.c. Heritage Status

For the purposes of this report, there are three parts of the building. a) a central core “The Hall” approximately 30 ft x 70 ft; b) a north addition “The Kitchen” approximately 12 ft x 54 ft; c) an east addition “The Stage” approximately 30 ft x 12 ft. The Hall and Stage are considered to have heritage value based on usage, but have no architectural or historical value. Because the Kitchen was not part of the original use or construction, it has no heritage value.

1.d. Building Bylaws

The Village of New Denver Building Bylaw No. 595, 2006 and amendments thereto provide building requirements for new buildings in the Village of New Denver. While these requirements are not used to determine whether or not Bosun Hall is in accordance to new building standards, climate and geological information is used when considering the structural integrity of the building. This information has been summarized in Table 1, below.

Table 1 - Climate and Geological Data, Village of New Denver Building Bylaw No. 595, 2006

Parameter		Design value
Temperature	2.5% Design Temp (January)	-24°C
	1% Design Temp (January)	-26°C
	2.5% Dry Bulb Temp (July)	33°C
	2.5% Wet Bulb Temp (July)	19°C
Degree days below 18°C		4303
Precipitation	Fifteen (15) minute rain	10mm
	One day rain	66mm
Max ground snow load		3.6kPa (75 lb/ft ²)
Associated rain load		0.1kPa (2.075 lb/ft ²)
Seismic Data	Zone Acceleration	1.00
	Zone Velocity	1.00kPa
	Zone Velocity Ratio (V)	0.05
Hourly Wind Pressures	1/10 probability	0.24kPa
	1/30 probability	0.30kPa
	1/100 probability	0.39kPa

2. Building Assessment

This building assessment is based on the condition of the building in July and August 2016. A detailed inspection was conducted by 9dot engineering inc. and Assured Homes Inspections Ltd. on July 6th, 2015, and can be found in **Appendix D**. Overall, the building appears to be in typical condition for a structure of its age and construction, requiring global minor repairs, and major repairs to the site conditions and lot grading, exterior walls, doors and windows, front balcony structure, roofing, insulation, crawlspace and overall structure integrity.

2.a. Site Analysis, Lot Grading, Drainage

Overall, Bosun Hall is built on a low slope property with drainage issues that are impacting the building foundation. Drainage of water towards the building on the South and North sides of the building can result in moisture damage and accelerated deterioration of the structure. A swale and collection system should be constructed to correct these drainage issues and move moisture away from foundation walls. In addition drainage/grade improvement on the East side of the building is advised to prevent drainage issues from worsening (Figure 2). It is recommended that perimeter footing drainage be installed when re-grading and foundation replacement are done.



Figure 2 - Site Grading East of Building

There are no existing retaining walls on the Bosun Hall property; however, the Village may wish to consider the addition of retaining walls in some areas of the site to improve grade and drainage as noted above.

2.b. Structure

During inspection, serious concerns requiring immediate repairs were noted regarding the building foundation, footings, and structure. Rot was prevalent throughout the structure extending from the foundation to subfloor structure, exterior and interior walls, ceiling, and attic.

Some of the deteriorating attic members were sistered to increase their strength; however, the sistered members were not sized to provide adequate support. Rafters in the Hall, Kitchen, and Stage, are 2"x 8" 18"OC, 2"x 6" 16" OC and 2"x 6" 24"OC respectively. Two of the stage rafters appear to have been reinforced with sistered members. The Kitchen rafters appear to have been toe nailed onto the north wall without a ledger board (Figure 3). These connections should be reinforced to properly secure the rafters to the main building structure.



Figure 3 - No Ledger Board @ Kitchen Rafters

The existing roof and rafters are sagging. It is recommended that a new truss system be installed when the roof is replaced, as attempting to improve the existing structural system would be difficult and costly to modify.

2.c. Foundation

Due to the age of the building and high moisture conditions, several indicators of foundation deterioration were noted during the inspection. These include differential movement, leaning and bulging, particularly at the South and West areas of the building. The North/East foundation appears to be performing as intended. The footings require moderate to significant repairs, and the footings at the north and midsection footings appear to have been undercut, likely by erosion over time. It was also not possible to locate a footing at the North East corner of the building.

Much of the foundation appears to be pressure treated wood foundation (PTW), which may require significant replacement. PTW must be kept dry to prevent rot and mildew issues; however, Bosun Hall's foundation is not properly protected from surface water and groundwater drainage and seepage, leaving the foundation structure vulnerable to deterioration (Figure 4). During the inspection, the foundation was noted to be rotting.

The existing PTW foundation has an estimated 25 year lifespan from time of installation, meaning that it is critically overdue for replacement. It is recommended that the existing PTW foundation be replaced with a new concrete foundation as soon as possible. This would include trenching, underpinning and levelling of the entire structure.



Figure 4 - PTW Foundation Rot Prevalent Around Entire Building

Partial dry rot was noted at the North East corner sill and rim joists (See Figure 5 below), requiring minor repairs to prevent the problem from worsening.



Figure 5 - North East Corner Sill Plate (Dry Rot)

During inspection of the interior building, it was also noted that the floor of the main hall appears to be sloping, indicating deterioration of the foundation below (Figure 6).




Figure 6 - Sloping Hall Floor

2.d. Basement and Crawl Space

The crawlspace under Bosun Hall was one of the most significant concerns noted during the site visit. The South/West areas of the crawlspace were not accessible during the inspection.

The main concern is the crawlspace has very limited access, which does not allow for detailed inspection or any further work under the building. The sloping main level floor indicates possible hidden moisture damage to the floor structure, and the excessive amounts of moisture present (Figure 7). Figure 7 also shows the electrical work in the basement (no junction boxes) and the sill plate sitting directly on the concrete foundation with no sill gasket. Standing water was visible beneath the building, and ventilation was inadequate and there was no vapour/moisture barrier. The crawlspace vents require wells and covers to prevent moisture intrusion into the crawlspace (Figure 8). Vents should be opened in the summer and remain closed in the winter. In addition, mechanical exhaust fans vented to the exterior of the building are required to reduce the humidity in the crawlspaces.



Figure 7 – Moisture Damage in Crawlspace and Electrical



Figure 8 - Crawlspace Vent

It is expected that major repairs will be required to the substructure of the building as there was evidence of moisture seepage, efflorescence, standing water, stains, mould, rot damage, peeling paint, swollen components and other issues that likely compromise structural integrity.

The addition of spray foam insulation at rim joists, floor joist or perimeter walls is also recommended to reduce heat loss through the substructure.

2.e. Building Envelope

Overall, the main deficiency noted in the building envelope was moisture and air flow control. Generally, replacing deficient or deteriorated building components and sealing any

holes, cracks or gaps will improve building performance. The components with the biggest impact at this time are the roof and siding which require repairs and replacement, and the crawlspace which is experiencing serious moisture concerns.

2.e.i. Roof

During the building inspection, access to the roof was limited due to the building height and steepness of the roof. Overall, the roof is in critical condition with significant permanent deflection (sag) in existing roof truss members. This sag is putting stress on the metal roofing and causing leaks. In addition to the metal roofing replacement, replacement of the underlying truss structure is required to correct sag and prevent further issues.

The roofing details for the three main areas of the building can be found in Table 2 below.

Table 2: Existing Roofing Details

	Stage	Hall	Kitchen
Slope	3/12	12/12	12/12
Sheathing	Solid shiplap boards	1"x6" strapping	1"x4" strapping
Underlayment	None	None	None
Material	Metal	Metal	Metal

The metal roofing is in very poor condition and should be replaced as soon as possible (Figure 10). There was no visible evidence of underlayment under any of the main roof sections, meaning the building envelope is vulnerable to condensation leaks and moisture penetration, and that installation of the new roofing material will also require installation of underlay. The existing metal roof was not installed correctly, and flashing is not properly preventing infiltration of moisture (Figure 9).



Figure 9 - Flashing at New Building Facade Installed Incorrectly




Figure 10 - Metal Roofing

There is also a flat Modified Bitumen Roofing (MBR) roof section over the main entrance to the building (Figure 11). Flashing at this section of the roof appears to have been installed incorrectly (backwards). In addition, the guardrails that were added to this roof section were surface mounted and have compromised the MBR, allowing leaks through to the roof structure to occur.



Figure 11 - MBR Roofing

It is recommended that the existing roof truss system be replaced to meet current code requirements. The long term deflection in the existing roof system likely cannot be corrected without compromising the structure. The metal roof should also be replaced, and the entire main roof should be re-sheathed with plywood. Underlayment should be installed, and the roofing should be replaced either with metal sheeting, laminated asphalt shingles, or Malarky shingles. Ice and weather shielding should be installed where applicable. In addition, repairs should be made to the interrupted MBR roofing over the

front entrance where it has been damaged by the guardrail installation. The flashing on the MBR section should also be repaired and replaced where needed.

For further information on the roof's structural condition, please see Section 2.g.

2.e.ii. Eaves Troughs

There are no existing eaves troughs or gutters installed on the building. As a result, roof drainage has damaged exterior walls and finishes, resulting in moisture penetration into the wall structures. Eaves troughs or snow stops are not recommended for this building, as snow must slide off the roof in order to prevent over loading of the roof structure (see Section 2.f).

2.e.iii. Exterior Walls

Overall, the exterior walls are in poor shape and all elements require either maintenance or immediate attention. The exterior walls are a combination of wood siding, stucco (Over wood siding) and Hardie Plank exteriors. The wood siding and stucco show significant signs of age, including staining, weathering and rot damage, and loose warped or cracked siding. The wood siding under the stucco appears to be in good condition in some areas (Figure 12).



Figure 12 - Stucco Over Original Wood Siding

The Hardie Plank siding appears to have been installed incorrectly with no flashing installed at the joints (Figure 13). There are indications of previous cosmetic repairs throughout the exterior walls, which indicates that there are ongoing problems which have not been solved, meaning deterioration will accelerate over time, resulting in higher maintenance costs. It is highly recommended wood siding is replaced and repaired where required instead of covered up. In addition, some of the siding should be removed to determine the extent of the damage to the internal wall structure.



Figure 13 - Hardie Plank Siding Separating @ Joints

The particular areas of concern include:

- Poorly installed stucco (overtop of shingle/dropsiding) should be removed and replaced.
- Hardie Plank siding installed incorrectly (no flashing at joints).
- Inadequate flashing on West and East walls causing moisture issues. Flashing should be installed or siding should be replaced.

Soil and debris should be cleared from areas where 6-8 inch's of clearance has not been met so that the structure can be properly checked for insect damage and rot below grade. Repair and replacement of soffits, fascia and window and door trim is also recommended as needed as much of these components exhibit evidence of rot or weather, or are missing. Caulking and flashing around some of the windows is inadequate and should be installed to prevent moisture intrusion at exterior walls. Installation of proper a proper vapour barrier in the exterior walls would improve the building envelope and reduce moisture infiltration.

2.e.iv. Windows

The windows at Bosun Hall are primarily wood framed, and are a mix of fixed and sliding windows with double glazed glass. Overall, the window condition appears to be adequate and does not require significant repairs or replacement at this time (Figure 14).




Figure 14 - West Facing Windows

2.e.v. Doors

The main entry and exterior door at the east end of the kitchen appear to be in good shape and will not require significant repairs; however, the exterior kitchen door on the South face of the building shows evidence of moisture and rot damage, and should be replaced and refinished.

2.e.vi. Foundation

As noted in **Section 2c** the crawlspace and foundation are not properly protected from moisture and the PTW foundation must be replaced. Proper drainage, moisture barriers and ventilation will help prevent the build-up of moisture that is currently causing issues in the foundation and floor substructure. Spray foam insulation at rim joists and crawlspace walls would also improve heat efficiencies of the building. Proper ground vapour barrier and insulation should also be installed.

2.f. Moisture Concerns

Moisture concerns were prevalent throughout the building, evidenced by mould, mildew, water stains and damp areas. In particular, the attics, crawlspace, and ceilings are not being properly ventilated or protected from exterior moisture infiltration. The biggest moisture concern is the crawlspace, while moisture concerns in the attic and ceiling are relatively low.

Moisture infiltration in the crawlspace is due to improper foundation seals, site and roof

drainage, plumbing leaks, and lack of ventilation. A moisture barrier should be installed in the crawl space along with a dehumidistat/ ventilation system. The site should also be re-graded to redirect drainage away from the foundation.

2.g. Porches, Decks and Balconies

Bosun hall has one balcony structure that extends out over the main entrance facing West (Figure 15), and a small deck at the east facing kitchen door (Figure 16).



Figure 15 - Front Balcony



Figure 16 - Side Deck

The balcony front entrance is only accessible through windows at the mezzanine level (not intended for occupancy) and is constructed of concrete and wood. It appears to meet code as a roof structure with no access. The structure itself requires some maintenance including the addition of lag screws to saddle brackets, and addition of a perimeter gutter. There is also evidence of potential rot at one of the columns (Figure 17). The guardrails on the balcony are incorrectly installed, as they are currently mounted on the decking. Rails should be correctly installed at the fascia boards (Figure 18).



Figure 17 - Dry Rot @ Balcony Post



Figure 18 - Balcony Guardrail

The side deck platform appears to be in good condition; however, there may be hidden damage as much of the deck underside was not visible for inspection. It is also recommended that the deck coating be replaced.

2.h. Interior Walls, Ceilings and Floors

The overall interior of the building is of moderate concern. Normal hairline cracks and slight damage can be seen on walls and ceilings, which can be repaired for aesthetic purposes, but are due to normal settling and slight seasonal shifting of the building. It is recommended that the regional building Inspector view stair rise/run and railings to ensure current code compliance.



Figure 19 - Mezzanine

Other aesthetic issues include slight mechanical damage and loose/cracked plaster. Dry water stains were noted on the ceiling in the mezzanine, indicating previous leakage and moisture issues (Figure 20). Damp water stains were noted in the men's bathroom around the toilet area, indicating current and ongoing moisture issues.



Figure 20 - Dry Moisture Stain on Ceiling

The flooring appears to be in moderately good shape, requiring minor maintenance and refinishing (softwood floor). During the inspection it was noted that the stair railing to the mezzanine area was loose (Figure 21). This is a potential fall hazard, and the railing should be brought up to code standards as soon as possible.



Figure 21 - Stairway to Mezzanine

2.i. Attic, Ventilation and Insulation

2.i.i. Overview

There are several attic sections in Bosun Hall, accessible through 3 ceiling hatches. Access to these areas was limited. During inspection evidence of past leakage through roof sheathing was noted. Paper vapour barrier is evident in the attic spaces, but the seal through the ceiling has been penetrated, reducing its effectiveness.

The existing attic hatches are not properly insulated, and allow warm moist air into the attics, where it condenses, potentially causing moisture issues. The hatches should be properly insulated and weather-stripped.

There appears to be a colony of red ants living in the primary attic (above the Hall at the West gable) (Figure 22). This type of ant is not typically destructive; however, the Village may wish to bring in an exterminator. Alternatively, the colony should be monitored to ensure that the nest does not become excessively large, or start to pose risk of damaging the structure. There is also a flicker nest on the south wall of the building.



Figure 22 - Ant Colony in Attic

2.i.ii. Ventilation

The attics are currently ventilated passively through box vents at the shed roofs and gable vents and ridge vents at the main gable roof (Figure 23). This is inadequate, and condensation issues and moisture were noted in the attic spaces. Increased ventilation through installation of soffit vents are recommended. This would improve air circulation in the attic, and may also help mitigate the potential of ice dam formation.



Figure 23 - Attic Gable Vent

2.i.iii. Insulation

Attic insulation has been installed inconsistently and is a combination of batt, blown cellulose and vermiculate.

The vermiculite insulation was found only in the attic above the kitchen. It should be noted that old vermiculite insulation in buildings in the Kootenays is likely to contain asbestos. While this is not an issue while the insulation is contained to the attic, **the insulation must be tested for asbestos prior to any work in the Kitchen attic space.** Removal of asbestos containing materials should only be undertaken by a trained professional.

Insulation should be moved from roof overhangs when soffit ventilation is installed to prevent insulation from blocking airflow (Figure 24).



Figure 24 - Insulation Covering Overhangs in Main Hall Roof

2.j. Kitchen and Bathrooms

The Bosun Hall kitchen appears to be in good condition, requiring some minor maintenance. The majority of these repairs and maintenance items are aesthetic, including refinishing the cupboards, sealing the counter to the backsplash, repairing the de-laminating counter, etc. During the inspection wet moisture evidence was found below the sink, and leaks were noted at the drain trap. It is recommended that this be repaired to prevent further moisture damage. It is also recommended that additional GFCI outlets be installed in the kitchen.

There are two bathrooms in Bosun Hall, currently being used as men's and women's bathrooms. Overall both bathrooms are in good condition, but both could benefit from the addition of a 30-minute timers to the bathroom fans, and the installation of GFCI outlets. The men's bathroom shows evidence of water stains and was noted having medium moisture content in the floor. The electric heater in the women's washroom is currently not working and should be repaired.

2.k. Heating and Cooling Systems

Bosun Hall is currently heated using electric convection heaters. Minor work is required to ensure that the heating system is maintained, however it would be recommended to have a

new mechanical system design to increase efficiency's and air movement and heating and cooling control. The heater in the women's washroom does not appear to be working, and the heaters in the bathrooms are old and should be considered for future replacement as they expend their usable lifespan.

An oil line is visible at the East exterior wall coming through the stucco. It is possible that there is a buried oil tank on the property, or that the oil tank was above grade and has since been removed.

2.l.Electrical System

The electrical system in Bosun Hall is in good condition, requiring little work. During the site visit it was noted that the 240V breaker was tripped at the electrical panel. **An electrician should be consulted to troubleshoot the issue.** The Village should also provide weatherproof protection on any exterior outlets. GFCI outlets in the bathrooms, kitchen and exterior are also recommended.

There was miscellaneous electrical noted throughout inspection where no junction boxes were installed. During future renovations, junction boxes should be installed when accessible. Additionally, it should be ensured that chairs and equipment are not stored in front of the electrical panel, as per code requirements.

Bosun Hall currently does not have hardwired smoke detectors. It is recommended that smoke detectors be hardwired in the main hall, mezzanine and loft.

2.m. Plumbing System

Overall, the plumbing system within the building requires replacements and upgrading. The Village has expressed desire to make additional bathrooms part of the renovation plan for this building, increasing the priority of bringing the existing water supply system up to standard. The existing piping network is comprised of ¾" galvanized steel pipe, which experiences low flows when multiple fixtures are in use. The existing interior drain piping is in good condition. An additional vent is recommended at the kitchen sink to the East side of the building.

Exterior hose bibs are not frost protected, and should be winterized to prevent damage.

Floor drains in the building are not currently doing a sufficient job at removing moisture. Sump pumps may be installed in the crawlspace to help control the runoff/groundwater issue in the short term. The Village may wish to undertake other repairs and mitigation efforts including grading of the lot, rerouting of drainage, and installation of a moisture barrier and humidistat in the crawlspace to see if the groundwater issue can be controlled by these methods; however, it is likely that some sump pumps will be required.

It should be noted that the septic tank and septic field used by Bosun Hall was not inspected as a part of this report. Records state that the septic tank was last pumped in 2012. There is also a septic field on the property, but the location and layout of the field are unknown. It is recommended that the field be located so that it can be assessed whether or not it will be adequate for the future renovation plans that The Village has in mind. There were no design drawings available to ensure that the septic system has adequate capacity for the number of bathrooms and maximum occupancy of the system. As a maintenance measure, it is recommended that the septic tank be pumped and cleaned every 5-7 years, or when the sludge level reaches 1/3 of the tank volume.

3. Proposed Renovations

At this time, it is recommended that repairs to the existing building be given the highest priority when considering how to allocate funding sources. The Village has also outlined a list of ideal renovations including:

- Washrooms accessible from both interior and exterior of building;
- Toilet and sink area for backstage;
- Dressing room backstage;
- Cost estimate of second set of full bathrooms near East end of building for decision making purposes;
- Removing storage areas from the front of the hall and using an extension at the back of the hall for better storage space, including space for chairs;
- Re-structuring stairs and access at the front of the hall to allow the upper mezzanine area to be used as an enclosed audio/video booth potentially including a viewing area,
 - Including a coat room and small utility room underneath mezzanine at front entrance;
- Creating more space at the back of the hall for backstage purpose;
- Patio or deck area to the north of the building with access into the hall that could be used as an outside dining area or bar,
 - Including consideration of roof line and traffic flow;
- Heating, insulation, electrical and lighting upgrades;
- Removal of false ceiling.

For the purposes of this report, general cost estimates will be provided; however, because no conceptual design of these potential renovations has been developed, lump sum general estimates will be provided. These estimates, included in Appendix B, do not take into account location or any design specifics and are simply rounded numbers to include the overall costs of these additions or repairs, and simply rough out the list of priorities.

It should be noted that many of the listed renovations may require an expansion of the existing septic system. A proper septic system assessment will be required before proceeding with these renovations, the results of which are not included in the budgetary numbers listed.

As noted earlier in the report, there may be a buried oil tank on site. While landscaping and site grading is being done, an effort should be made to locate any old oil or gas tank with a metal detector. If the metal detector does not result in any findings, it can be assumed that there are no existing steel tanks on the property.

It should be noted that any major renovations and changes to the structure will require that the building meet required fire codes as noted by the fire inspector's report from 2015. **For renovations that change layout or the function of the building the Village should do walkthrough with a Fire Inspector and/or Code Consultant to identify any code requirements that may need to be updated.**

4. Recommendations

The following renovations/modifications should be planned and budgeted for and completed as soon as possible:

1. New building foundation, grading and drainage of site
2. Paint and restore siding to keep moisture away from wall structural components – new siding where required
3. New complete roof structure and roofing and insulation

These items are considered most crucial for maintaining the structural integrity of the building, and are listed in order of urgency.

During all renovations and construction undertakings, the Village is advised to proceed with caution, as many of the building components may contain hazardous materials, and as such should be handled and disposed of with care. Components of particular concern include ceiling tiles and insulation (asbestos) and ceiling paint (lead).

5. Conclusion


Overall, Bosun Hall exhibits serious structural and foundation/drainage issues that need to be addressed prior to pursuing renovations to improve the functionality and aesthetics of the building. The roof trusses, roofing material, and parts of the foundation require replacement as outlined in this report. These major renovations are anticipated to cost \$547,500.

In addition to the major work described above minor additional work including maintenance upgrades, minor repairs and further consultation can be expected to add approximately \$150,000 to project costs.

Several other minor renovations and repairs are recommended to improve the building and ensure that it continues to be usable in future years. The renovation 'wish list' provided by the Village of New Denver has been included for record keeping purposes and very rough unit price estimates have been included for options to help direct future planning and financing.

The next step for Village of New Denver to address the recommendations in this report is detailed design and tender for the scope of work. Once the budget has been confirmed and funding has been secured, the Village should consult with 9dot Engineering Inc. and any authorities having jurisdiction (eg. building inspector) as needed, before proceeding with major renovations.

Appendix A – Drawings




SITE LAYOUT - N.T.S.


Project		VILLAGE OF NEW DENVER BOSUN HALL	
Stamp			
Drawing		SITE LOCATION AND SETTLING POND LAYOUT	
Date:	16.09.01	Project No.:	16-013
Designed By:	ST	Drawing File:	16-013-A
Drawn By:	JT	Scale:	AS NOTED
Checked By:	ST	Sheet No.:	C1
Approved By:	ST	Issue/Rev:	A

DO NOT SCALE DRAWINGS
Written dimensions shall govern.


COPYRIGHT: All designs, calculations and drawings are the intellectual property of the Village of New Denver. No part of this package are the intellectual property of the Village of New Denver. No part of this package may be reproduced or transmitted in any form or by any means electronic or mechanical, including photocopying, recording, or by any information storage and retrieval system, without the written consent of the Village of New Denver Engineering Inc.



Date:	16.09.01	Project No.:	16-013
Designed By:	ST	Drawing File:	16-013-A
Drawn By:	JT	Scale:	AS NOTED
Checked By:	ST	Sheet No.:	S2
Approved By:		Issue/Rev.:	A



WEST - FRONT ELEVATION



NORTH ELEVATION

Project		VILLAGE OF NEW DENVER BOSUN HALL		Drawing	
Date: 18.09.01		Project No.: 18-013		Drawing File: 18-013-A	
Designed By: ST		Scale: AS NOTED		Sheet No.: 18-013-A	
Drawn By: JT		Checked By: ST		Issue/Rev:	
Approved By: ST		S3		A	
FRONT & SIDE ELEVATIONS					
DO NOT SCALE DRAWINGS Written dimensions shall govern.					
COPYRIGHT: All designs, calculations and drawings are the intellectual property of the Village of New Denver. No part of this package can be reproduced without the written consent of the Village of New Denver. Engineering Inc. and CANNOT be used in part or in whole without the written consent of the Village of New Denver. Engineering Inc.					
No.		Date		Revision	
A		JULY 05/15		CONSTRUCTION BUDGET	
No.		Date		Issue	

Appendix B – Renovation Plan Budget

16-013 Bosun Hall Renovation Plan

Estimated Cost Breakdown - Class C

November 18, 2016

Major Renovations

Site Item	Notes	Cost Estimate
Perimeter drainage and re-grading	Excavate, waterproof, add drainage, backfill	\$20,000.00
Removal of vermiculite insulation	May contain asbestos. Complete during Roof Replacement	\$50,000.00
Roof Replacement	Including: Remove and dispose of existing roofing material Soffit ventilation Installation/completion of roof sheathing (1/2") New metal roof	\$75,000.00
New truss system	Installed during metal roof replacement	\$17,500.00
New foundation & lift building	New concrete foundation to replace PTW.	\$250,000.00
Exterior siding replacement	Remove stucco and replace siding. Investigate wall structure condition.	\$125,000.00
Basement moisture management	Including proper mechanical ventilation and 2-3 sump pumps	\$10,000.00
Sub Total Major Renovations		\$547,500.00

Maintenance and Upgrades

Site Item	Notes	Cost Estimate
Replace/Install flashing as necessary		\$7,500.00
Replacement of balcony guardrails	Including proper flashing and patching of decking	\$5,000.00
New heating and ventilation system & upgrade electrical		\$55,000.00
Refinish hardwood floor		\$45,000.00
Insulate and weather strip attic hatches		\$1,000.00
Add GFCI to bathroom, kitchen and outdoor outlets	Assuming 2 outlets	\$1,500.00
Exterior ventilation in bathrooms		
Hardwired fire alarms	Install in main hall, mezzanine and loft.	\$5,000.00
Winterize exterior hose bibs		\$2,000.00
Sub Total Medium Maintenance		\$122,000.00

Minor Repairs

Site Item	Notes	Cost Estimate
Repair heater in womens washroom		\$500.00
Interior aesthetic repairs	Including replastering and painting of interior walls and ceilings	\$20,000.00
Sub Total Minor Repairs		\$20,500.00

Further Consultation

Site Item	Notes	Cost Estimate
Hazardous Substances	Check existing vermiculite insulation for asbestos. (Testing only)	\$2,500.00
Breaker Diagnostic	240V nuisance tripping	\$500.00
Sub Total Further Consultation		\$3,000.00

Renovation Options

Site Item	Notes	Cost Estimate
New Septic System	Will accommodate addition bathrooms	\$60,000.00
Stand-alone Washrooms	Seperate from building	\$40,000.00
Dressing Room Addition	Backstage	\$25,000.00
Washroom Area Backstage		\$35,000.00
Storage Area Removal @ Front of Hall		\$10,000.00
Stair Restructuring		\$5,000.00
Extension to Back of Hall	Storage at back of hall with space for chairs	\$50,000.00
Patio or Deck at North of Building	Consider roofline and traffic flow	\$25,000.00
Removal of False Ceiling		\$25,000.00
Sub Total Renovation Options		\$275,000.00

Total Price **\$968,000.00**

Appendix C – Fire Safety Inspection Form

FireWise Consulting Ltd.
 PO Box 253 Shawnigan Lake, BC
 V0R 2W0
 250-812-9636
 or 250-812-9830
 email: fwcinsp@gmail.com



FIRE SAFETY INSPECTION FORM

Municipality: New Denver	Folio Number
Inspected by: Bob Turley	Email address fwcinsp@gmail.com Phone: 250-812-9636
Date of Inspection: June 8, 2015	Date of Last Inspection Sept 17, 2013
Premise Name: Bosun Hall	Property Owner: Village of New Denver
Premise Address: 710 Bellevue Street, New Denver, BC V0G 1S0	Address: 115 Slocan Avenue, New Denver, BC V0G 1S0
Phone: 250-358-2396	Phone: 250-358-2316
Email Address	Email Address:
Emergency Contact Name Leonard Casley	Emergency Contact#: 250-358-7742 (Leonard)
Building Type A2 Assembly Community Hall	

	Satisfactory	Unsatisfactory	N/A
1. Address Posted	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Yard Area	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Firefighting vehicle access	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Fuel tanks on property	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
5. Lock Box	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
6. Exterior white lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Smoking area	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

8. Refuse disposal	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Egress exits	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Exit doors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Exit corridors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Exit Stairways	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Emergency Lights	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. Electrical General	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Electrical Room	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
16. Mechanical Room	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
17. Storage Room	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Hazardous Materials storage	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
19. Laundry Room	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
20. Fire separation/doors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Housekeeping	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Refuse Chute	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
23. Fire Safety Plan	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
24. Occupant Load Posted	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
25. Fire Alarm System	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Fire Alarm Monitored	Monitored by:		
Serviced	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Next Service Due			
26. Sprinkler System	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Next Service Date			
27. Standpipe System	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Next Service Date			
28. Portable Fire Extinguishers	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
29. Commercial Kitchen Equip.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
30. Heating System	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Type electric wall mount			

Corrections to be completed

- 13.** Emergency lights are due for annual inspection and testing by a qualified technician. Records of inspection and testing must be made available upon request and tags should be attached to the unit indicating when the last service was performed. The work required under this section should be completed within 60 days.
- 23.** A fire Safety Plan should be developed in conformance with section 2.8 of the BC Fire Code. The work required under this section should be completed by the next regular inspection.
- 24.** In assembly occupancies with occupant loads exceeding 60 people the occupant load must be posted in a conspicuous location near the principal entrance to the room or floor area. The work required under this section should be completed by the next regular inspection.
- 28.** Fire extinguisher behind the door in the storage room should be relocated to be readily available when needed. The work required under this section should be completed within 60 days.
- 29.** The kitchen is not compliant with the National Fire Protection Association (NFPA) 96: Standard for Ventilation Control and Fire Protection of Commercial Cooking Operations. The current use of the kitchen does not produce grease laden vapours so full compliance with the requirements for a commercial kitchen has not been required. The kitchen was clean at the time of inspection and there was no indication of a build-up of grease. Should this change compliance with NFPA 96 may be required.

This is to certify that on the above date this premise was inspected and the conditions were found as stated.

Inspector's Signature



Unless otherwise specified, the owner or the owner's authorized agent is responsible for complying with the BC Fire Code. Persons guilty of an infraction of the Fire Prevention By-laws, Fire Services Act, or the B.C. Fire Code are liable to the penalties and/or conditions defined in those regulations.

If you have questions about this inspection please call Fire Chief/Local Assistant Fire Commissioner Leonard Casley 1-250-358-2316.

Appendix D – Assured Home Inspection Ltd. Building Inspection (2016)

Assured Home Inspections Ltd.
304 Gore St.
Nelson, BC
Residential and Commercial Inspections



710 Bellevue St. New Denver, BC

Building Survey Inspection
Report # 2016-102

Prepared for:
9dot Engineering Inc.

Prepared by:
Greg Tromans RHI
CPBC Licence #47893

Assured Home Inspections Ltd.
Residential and Commercial Inspections
304 Gore St. Nelson, BC V1L 5B7
Telephone: 250.352.6233

Report # 2016-102

July 6, 2016

Attention:

Steven Thomson and Justine Thielker
9dot Engineering Inc.

RE: Inspection of 710 Bellevue St. New Denver, BC

Introduction:

As per the request of Steven Thomson and Justine Thielker (9dot Engineering Inc.) and in accordance with the proposal date of July 6, 2016. A visual inspection at 710 Bellevue St. New Denver, BC was conducted to identify the existing conditions of the following components:

- Structure
- Heating and Cooling Systems
- Plumbing Systems
- Ventilation Systems
- Insulation
- Roofing Systems
- Exterior Components
- Interior Components

This report is for the intended use of my client. Use of the information contained within the report by any other party is not intended and therefore, I accept no responsibility for such use.

This report is considered to be preliminary in nature. Before any major repairs are undertaken, I recommend that a specialist perform a detailed survey and develop a plan of action.

The site review of this inspection was not conducted. The inspection was limited to components that were readily visible and not obstructed by storage, finishes, vegetation etc.

Access was gained to all areas of the building, except to the south half and westerly portion of the north half of the crawlspace area of this building. Further evaluation of these areas is highly recommended, due to known and unknown below grade conditions of the substructure of this building.

Only items specifically addressed in this report were examined. No comment is offered on building code, building bylaw compliance, fire alarms and sprinkler systems. Recommend a review with the Village of New Denver, RDCK Building Inspection Department and RDCK Fire Department prior to occupancy of the building.

Report Limitations:

This report is intended only as a general guide to help the clients make their own evaluation of the overall condition of the commercial building and is not intended to reflect the value of the premises, nor make any representation as to the advisability of the purchase. The report expresses the opinions of the inspector, based upon his visual impressions of the conditions that existed at the time of the inspection only. The inspection and the report are not intended to be technically exhaustive, or to imply that every component was inspected, or that every possible defect was discovered. No disassembling of equipment, opening of walls, moving of furniture, appliances or stored items, building materials or excavation was performed. All components and conditions which by nature of their location are concealed, camouflaged or difficult to inspect are excluded from the report.

Systems and conditions which are not within the scope of the inspection include, but are not limited to: formaldehyde, lead paint, asbestos, toxic or flammable materials and other environmental materials and other environmental hazards, pest infestations, efficiency measurement of insulation or heating and cooling equipment, internal or underground drainage or plumbing, any system that is otherwise secure, water wells (water quality or quantity) zoning ordinances; intercoms; security systems; heat sensors; cosmetics or building code conformity. Any general comments about these systems and conditions are informational only and do not represent an inspection.

The inspection report should not be construed as a compliance inspection of any governmental or non governmental codes or regulation. The report is not intended to be a warranty or guarantee of the present or future adequacy or performance of the structure, it's systems, or their component parts. This report does not constitute any express or implied warranty of merchantability or fitness for use regarding the condition of the property and it should not be relied upon as such. Any opinions expressed regarding adequacy, capacity, or expected life of components are general estimates based on information about similar components; occasional wide variations are to be expected between such estimates and actual experience.

To the best of my knowledge and belief, all statements and information in this report are true and correct. Please take time to review the details of the subject building, which are within the body of this report.

Thank you for selecting my firm to do the building evaluation. If you have any questions regarding the inspection report or the building, please feel free to call me. I can be reached at 250.352.6233

Greg Tromans RHT



TABLE OF CONTENTS

GENERAL

Property Inspection Contract
General Information
Rating System Definitions

1.0 GROUNDS

1.1 Site Conditions
1.2 Garage/Carport

2.0 EXTERIOR

2.1 Exterior Walls
2.2 Exterior Doors & Windows
2.3 Porches & Decks
2.4 Balconies
2.5 Solariums, Patios, & Elevated Walkways

3.0 ROOFING AND ATTIC

3.1 Roofing
3.2 Attic, Ventilation & Insulation

4.0 INTERIOR

4.1 Interior Walls, Ceilings & Floors
4.2 Kitchen
4.3 Bathroom(s)
4.4 Laundry Facilities
4.5 Ventilation & Condensation
4.6 Fireplace(s)
4.7 Basement & Crawl space

5.0 STRUCTURE

6.0 PLUMBING SYSTEM

6.1 Water Supply and DWV (Drain/Waste/Vent)
6.2 Hot Water Supply

7.0 ELECTRICAL SYSTEM

8.0 HEATING & COOLING SYSTEM

9.0 SUMMARY

10.0 APPENDICES

Maintenance Tips

GENERAL INFORMATION

REF # 2016-102

CLIENT INFORMATION

CUSTOMER NAME(S): 9dot Engineering Steven Thomson

CUSTOMER ADDRESS: EMAIL:

WORK # 505-8261 HOME # FAX # CELL # 250.777.1565

REFERRED BY

- ☐ Lender/mortgage broker
☐ Brochure/flyer
☒ Previous client
☐ Friend/family

- ☐ FTHB seminar
☐ Realtor
☐ Lawyer/notary
☐ Yellow Pages
☐ Web Page

NAME OF REFERRAL SOURCE

WORK # CELL #

FAX # PAGER #

INSPECTION INFORMATION

INSPECTION DATE July 6/16

TIME STARTED 9:20 AM/PM

TIME COMPLETED 3:30 AM/PM

PRESENT DURING THE INSPECTION:

- ☐ Purchaser ☐ Present for review of findings at end of inspection only
☐ Selling Agent ☐ Present for review of findings at end of inspection only
☐ Listing Agent
☐ Vendor
☐ Tenant

WEATHER CONDITION Temperature +20 °C

- ☐ Raining ☐ Clear
☐ Recent rain ☒ Overcast
☐ Snow ☐ Windy
☒ Dry ☐ Partly cloudy

SOIL CONDITION

- ☒ Damp ☐ Snow covered
☐ Wet ☐ Frozen
☐ Dry

TYPE OF INSPECTION

(Please refer to applicable Professional Association Standards of Practice & Code of Ethics)

- ☐ HOUSE INSPECTION ☒ OTHER
☐ CONDOMINIUM APARTMENT / TOWNHOUSE INSPECTION ☐ Structural components ☐ Roof only
☐ NEW CONSTRUCTION PRE-DELIVERY INSPECTION (PDI) ☐ Problem investigation ☐ Foundation/basement/crawl space
☐ IAQ investigation ☐ Mechanical/electrical components

PROPERTY INFORMATION

ADDRESS 710 Bellevue St. MUNICIPALITY New Denver, BC ☒ Urban ☐ Semi-rural ☐ Rural

BUILDING TYPE ☐ Residential ☐ Detached ☐ Duplex ☐ Triplex ☐ Fourplex ☒ Other
☐ Commercial ☐ Townhouse ☐ Mobile home
☐ Leisure/sport ☐ Apartment
☐ Farm
STORIES ☐ 1 ☐ 2 ☐ 3
☒ 1 1/2 ☐ 2 1/2 ☐ Other
EST. SQ.FT. EST. AGE 1900+

BASEMENT/CRAWL SPACE ☐ Full basement ☐ Fully finished ☐ Partially finished ☐ Not finished
☐ Partial basement ☐ Slab on grade ☐ Underground garage
☒ Crawl space
SECONDARY LIVING UNITS ☐ Yes, # units: ☒ No
PROPERTY ☒ Occupied ☐ Vacant ☐ Unoccupied but completely/partially furnished

ORIENTATION (faces approx.) ☐ North ☐ South ☐ East ☐ West S/W

PUBLIC SITE IMPROVEMENTS ☒ Paved roads ☐ Sidewalks ☐ Open ditch ☐ Telephone
☒ Gravel roads ☐ Curbs ☐ Street lights

SPECIAL INSTRUCTIONS

All buyers are advised to carefully read the Property Condition Disclosure Statement (PCDS) and obtain written confirmation or receipts for any major repairs done to the property.

Condominium apartment or townhouse buyers are advised to thoroughly review a minimum of two (2) years of Strata and AGM Minutes.

When reviewing these Minutes, the buyers are advised to highlight and bring to the inspector's attention any mention of membrane failure, flashing failure, leaks, roof problems, hot water problems, plumbing leaks, any reference to an engineering report, balcony related problems, garage leaks, exterior wall (envelope) problems, planters, etc.

Buyers should obtain copies of any engineering report(s) or details of any major repairs or replacement.

RATING SYSTEM DEFINITIONS

RATING	1	2	3
FUNCTIONAL/SATISFACTORY <ul style="list-style-type: none"> No problems / deficiencies observed at time of inspection. Item, component or system appears to be adequately performing its intended function. Regular monitoring and servicing of item, component or system is required in order to ensure continued satisfactory performance. 			
MAINTENANCE REQUIRED <ul style="list-style-type: none"> Minor problems / deficiencies observed at time of inspection. Item, component or system appears to be currently operational/functional but requires minor repairs or maintenance. Lack of timely repairs or maintenance will eventually necessitate replacement of item, component or system but does not immediately affect the home's habitability. Regular monitoring and servicing of item, component or system is required in order to ensure continued satisfactory performance. 			
POOR/UNSATISFACTORY <ul style="list-style-type: none"> Major or potentially major problems / deficiencies observed at time of inspection. Item, component or system is significantly deficient (poor/bad condition), is not performing as intended, or is nearing the end of its service life. Item, component or system requires replacement or major repairs. If condition not repaired or corrected, may result in property damage or personal injury. 			

OTHER TERMINOLOGY USED IN THIS REPORT

- ◆ **FURTHER INVESTIGATION REQUIRED:** Minor to major problems may exist. Scope of the problems cannot be identified at time of inspection. Destructive testing may be required. Strongly recommend further investigation with a licensed specialist/contractor prior to purchase.
- ◆ **NOT VISIBLE:** Items, components or systems marked "not visible" are either concealed or inaccessible and cannot be inspected. Therefore, the inspector cannot provide an opinion as to their condition and/or functionality. Any item, component or system that is "shut down" is not activated by the home inspector. It is recommended that you obtain assurance or demonstration from the vendors that the items, components or systems are operational and in good order. Otherwise, arrangements should be made before closing to have these items, components or systems fully evaluated by a specialist.
- ◆ **NOT APPLICABLE:** Items, components or systems marked "N/A" are not present in this home.

1.1 SITE CONDITIONS			1	2	3	REF #
OVERALL GRADE & SITE DRAINAGE GRADE <input type="checkbox"/> Flat <input checked="" type="checkbox"/> Low slope <input type="checkbox"/> Medium slope <input type="checkbox"/> Steep slope SITE DRAINAGE <input type="checkbox"/> Flat <input checked="" type="checkbox"/> On slope <input type="checkbox"/> Terraced <input type="checkbox"/> Hilltop <input type="checkbox"/> In valley ♦ This inspection does not address geotechnical or site stability issues. <input type="checkbox"/> Planters at foundation					<input checked="" type="checkbox"/>	♦ Negative slope towards building is not conducive to drainage <input type="checkbox"/> Site erosion visible / Consult soils engineer <input checked="" type="checkbox"/> Runs towards building on <u>South, North</u> <input checked="" type="checkbox"/> Drainage / grade improvement is advised <input type="checkbox"/> Standing / ponded water <u>East</u> <input checked="" type="checkbox"/> Earth / concrete-to-wood contact visible <input checked="" type="checkbox"/> Soil level too high at foundation <input type="checkbox"/> Walkways settled towards foundation
UNDERGROUND OR FOOTING DRAINS ♦ Underground portions not visible <input type="checkbox"/> Interior / exterior sump (See Section 6.1 - Plumbing)			<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Sediment visible in drains ♦ Cleaning of drains now and periodically is advised (see below) ♦ Backwater valve not checked
DOWNSPOUT DRAIN CONNECTIONS ♦ See Section 3.1 - Roofing page 2			<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Add downspout leaders <input type="checkbox"/> Add splash blocks <input type="checkbox"/> Re-connect to drains
STAIRS / WINDOW WELLS <input type="checkbox"/> Proper drainage cannot be confirmed			<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Provide / clean drain <input type="checkbox"/> Add drain cover <input type="checkbox"/> Add guard / hand rails @ _____ <input type="checkbox"/> Unequal rise / run at stairs
♦ Determining the condition of underground drains is beyond the scope of this inspection. Consult drainage specialist for complete evaluation. <u>C/S Vents need wells and covers to prevent moisture intrusion</u>						
DRIVEWAY <input type="checkbox"/> Lane <input type="checkbox"/> Steep <input type="checkbox"/> Snow covered			<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Cracked / settled / heaved / trip hazard <input type="checkbox"/> Repair / replace <input type="checkbox"/> Minor spalling <input type="checkbox"/> Affected by tree roots <input type="checkbox"/> Apply sealant
WALKWAYS <input type="checkbox"/> Not visible/Snow covered			<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Cracked / settled / heaved / trip hazard <input type="checkbox"/> Fill cracks <input type="checkbox"/> Wood spacers rotted
<input type="checkbox"/> Install guard / hand rails @ all exterior stairs <u>Possible installation of retaining walls in areas of site to improve grade / and swales @ site.</u>						
FENCES			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Adjust / repair / replace gate(s) <input type="checkbox"/> Replace post / rails as necessary <input type="checkbox"/> Leaning / fallen down / rot damage <input type="checkbox"/> Paint or stain to extend life
<input type="checkbox"/> Foliage / debris / stored material covers fence - unable to fully inspect <input type="checkbox"/> Apparent insect / rot damage to fence / gate			<input type="checkbox"/> Fence height at pool / spa is too low for safety <input type="checkbox"/> Self-closing device missing / not working around pool / spa			
RETAINING WALLS <input type="checkbox"/> Proper drainage cannot be confirmed			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Leaning / bulging / cracking / deteriorated <input type="checkbox"/> Add weep holes <input type="checkbox"/> Install guardrail
LANDSCAPING <input type="checkbox"/> Pool / pond / hot tub - not inspected			<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/> Trim vegetation: roof / power lines / building surfaces <input checked="" type="checkbox"/> Remove trees planted close to structure
OUTBUILDINGS			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Removal recommended <input type="checkbox"/> Soil contact at building walls - rot damage <input type="checkbox"/> Roof damaged
<input type="checkbox"/> Vent / fill pipe visible @ _____ Possible buried oil tank: locate, test for residual oil products & dispose according to applicable municipal requirements.						

1.2 GARAGE/CARPORT			1	2	3	REF # 2016-102
<input type="checkbox"/> GARAGE <input type="checkbox"/> No access	<input type="checkbox"/> CARPORT	<input type="checkbox"/> Single car <input type="checkbox"/> Double car <input type="checkbox"/> Triple car	<input type="checkbox"/> Detached <input type="checkbox"/> Attached <input type="checkbox"/> Tuck under	<input type="checkbox"/> U/G PARKING (see Sections 4.7 & 5.0) <input type="checkbox"/> Thorough inspection limited by stored items / foliage		
ROOF STYLE		<input type="checkbox"/> Flat <input type="checkbox"/> Hip	<input type="checkbox"/> Gable	<input type="checkbox"/> Deck over (See Section 2.3 - Porches & Decks) <input type="checkbox"/> Roof part of main house construction (see Section 3.1 - Roofing) *		
ROOF STRUCTURE <input type="checkbox"/> Part of main building (See section 3.1 - Roofing)		<input type="checkbox"/> Engineered truss <input type="checkbox"/> Stick built <input type="checkbox"/> Not visible	<input type="checkbox"/> Attic area access <input type="checkbox"/> Access hatch <input type="checkbox"/> No access hatch	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Rot / structure damage <input type="checkbox"/> Rafters / ridge sagging <input type="checkbox"/> Add attic hatch / hatch cover
ROOF MATERIAL <input type="checkbox"/> Part of main building (See section 3.1 - Roofing)		<input type="checkbox"/> BUR <input type="checkbox"/> Torch-on <input type="checkbox"/> Metal	<input type="checkbox"/> Asphalt shingles <input type="checkbox"/> Wood <input type="checkbox"/> Tile	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Leaks noted - repair ASAP <input type="checkbox"/> Replacement recommended <input type="checkbox"/> Clean debris off roof
GUTTERS <input type="checkbox"/> Part of main building (See section 3.1 - Roofing)		<input type="checkbox"/> Metal / Plastic <input type="checkbox"/> Wood	<input type="checkbox"/> Hidden / EPDM <input type="checkbox"/> Roof drains	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Cleaning required <input type="checkbox"/> Repair / replace / add
WALL STRUCTURE		<input type="checkbox"/> Wood frame / Metal	<input type="checkbox"/> Not visible	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Rot / deterioration
SIDING & TRIM <input type="checkbox"/> Part of main building (See Section 2.1 - Ext. Walls)		<input type="checkbox"/> Brick / Wood <input type="checkbox"/> Stucco <input type="checkbox"/> Vinyl / Metal	<input type="checkbox"/> Window(s)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Repair / replace siding / trim <input type="checkbox"/> Soil / concrete / asphalt contact - possible rot / insect damage
FOUNDATION <input type="checkbox"/> None / Not visible		<input type="checkbox"/> Concrete <input type="checkbox"/> Brick	<input type="checkbox"/> Block <input type="checkbox"/> Stone	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Normal cracks or slight settlement <input type="checkbox"/> Major cracking / settlement <input type="checkbox"/> Add / tighten anchor bolt nuts
FLOOR		<input type="checkbox"/> Concrete <input type="checkbox"/> Gravel / dirt	<input type="checkbox"/> Asphalt	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Normal cracks / minor slab settlement <input type="checkbox"/> Major slab settlement / heaving <input type="checkbox"/> Concrete spalling
AIR-TIGHT SEPARATION ♦ Cannot confirm compliance to fire code		<input type="checkbox"/> Interior unfinished <input type="checkbox"/> Finished on: <input type="checkbox"/> Ceiling / wall	<input type="checkbox"/> Gypsum wallboard <input type="checkbox"/> Stucco <input type="checkbox"/> Wood siding	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Stains noted on ceiling - possible leaks <input type="checkbox"/> No air-tight seal at wall / ceiling - install now <input type="checkbox"/> Repair holes / tape joints
GARAGE DOORS No: _____ <input type="checkbox"/> Wood / masonite <input type="checkbox"/> Metal <input type="checkbox"/> Vinyl-clad		<input type="checkbox"/> Hinged / folding <input type="checkbox"/> Overhead <input type="checkbox"/> Automatic opener <input type="checkbox"/> Electric eye / Door edge sensor <input type="checkbox"/> Key-in access only	Auto reverse function: <input type="checkbox"/> Tested <input type="checkbox"/> Not tested <input type="checkbox"/> Disconnected <input type="checkbox"/> None	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Door(s) locked / blocked - unable to test <input type="checkbox"/> Adjust / Repair / Replace - door <input type="checkbox"/> Adjust / Repair / Replace - hardware <input type="checkbox"/> Adjust / repair auto reverse function ASAP <input type="checkbox"/> Install outlet / eliminate extension cord ♦ Remote control devices not checked
HOUSE DOOR <input type="checkbox"/> N/A		<input type="checkbox"/> Solid / hollow wood <input type="checkbox"/> Panel <input type="checkbox"/> Metal	<input type="checkbox"/> With glazing <input type="checkbox"/> With deadbolt <input type="checkbox"/> Automatic closer	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Repair / adjust door / hardware <input type="checkbox"/> Add / repair automatic door closer <input type="checkbox"/> Improve to fire rated door system <input type="checkbox"/> Replace / install weather stripping
SERVICE DOOR <input type="checkbox"/> N/A		<input type="checkbox"/> Solid / hollow wood <input type="checkbox"/> Panel <input type="checkbox"/> Metal	<input type="checkbox"/> With glazing <input type="checkbox"/> With deadbolt <input type="checkbox"/> Add deadbolt	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Repair / adjust door / hardware <input type="checkbox"/> Moisture damage to door / jamb / threshold / trim - repair / replace <input type="checkbox"/> Replace / install weather stripping
ELECTRICAL		<input type="checkbox"/> Outlets / GFCI <input type="checkbox"/> Light fixtures	<input type="checkbox"/> Electrical panel(s) <input type="checkbox"/> _____	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Surface or temporary wiring needs correction <input type="checkbox"/> * See Section 7.0 - Electrical System
PLUMBING / HEATING		<input type="checkbox"/> N/A		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Exposed pipes may freeze
GRADE / SLOPE / DRAINAGE <input type="checkbox"/> Drive slopes towards garage / carport		<input type="checkbox"/> Drain not connected <input type="checkbox"/> Catch basin		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Install full garage width catch basin <input type="checkbox"/> Clean catch basin
<input type="checkbox"/> CONDOMINIUM INSPECTION: Review Strata Council Minutes for references to problems such as water infiltration, membrane failure, etc. and for any mention of past and/or future repairs, replacement and maintenance information. Obtain copies of any engineering reports						

Oil kne visible @ East Exterior wall → stucco

2.1 EXTERIOR WALLS <i>see sec. 8.0</i>		1	2	3	REF # <i>2016-102</i>
PRIMARY WALL SURFACE <input checked="" type="checkbox"/> See Below <input checked="" type="checkbox"/> Wood / Hardie Plank <input checked="" type="checkbox"/> Stucco <input type="checkbox"/> Vinyl <input type="checkbox"/> Brick veneer <input type="checkbox"/> Masonry	<input type="checkbox"/> Asbestos shingle <input type="checkbox"/> Stone <input type="checkbox"/> Metal <input type="checkbox"/> Concrete <input type="checkbox"/> EIFS	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Evidence of recent painting/repairs <input checked="" type="checkbox"/> Siding loose/buckled/warped/cracked <input checked="" type="checkbox"/> Stained/weathered/rot damage (see below) <input type="checkbox"/> Mortar deteriorated/cracked <input type="checkbox"/> Weep holes blocked/missing
OTHER SURFACE <input checked="" type="checkbox"/> See Below <input checked="" type="checkbox"/> Wood / Hardie Plank <input type="checkbox"/> Stucco <input type="checkbox"/> Vinyl <input type="checkbox"/> Brick veneer <input type="checkbox"/> Masonry	<input type="checkbox"/> Asbestos shingle <input type="checkbox"/> Stone <input type="checkbox"/> Metal <input type="checkbox"/> Concrete <input type="checkbox"/> EIFS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Evidence of recent painting / repairs <input checked="" type="checkbox"/> Siding loose/buckled/warped/cracked <input type="checkbox"/> Stained/weathered/rot damage (see below) <input type="checkbox"/> Mortar deteriorated/cracked <input type="checkbox"/> Weep holes blocked/missing
<input checked="" type="checkbox"/> Inspection method(s) used to observed the exterior wall elevations: <input checked="" type="checkbox"/> From ground <input checked="" type="checkbox"/> From ground with binoculars <input type="checkbox"/> From decks / windows <input type="checkbox"/> From roof /ladder <input type="checkbox"/> Other					
<input checked="" type="checkbox"/> Seal all openings/holes in siding <input type="checkbox"/> Install new dryer vent hood at exterior wall					
<input checked="" type="checkbox"/> Buildings with little or no roof overhang are susceptible to water penetration and rot damage. Wall areas on the side of prevailing winds, around windows, doors and other openings, as well as balconies, rails, wall protrusions, and any areas where dissimilar materials connect are particularly vulnerable.					
<input checked="" type="checkbox"/> Removal of siding in suspect areas is required to determine the extent of any damage. POSSIBLE MAJOR PROBLEMS.					
<input checked="" type="checkbox"/> Consult engineering firm specializing in building envelope evaluation.					
<input checked="" type="checkbox"/> CONDOMINIUM INSPECTION: Review Strata Council Minutes for references to past and/or future repairs or replacement. Obtain copies of any engineering reports. Refer to Special Instructions on the General Information page at the beginning of this report.					
<i>interface @ Roof/wall</i> <i>2-3" clearance needed</i> <i>- Hardie plank type siding → incorrect installation → No Flashing @ joints</i> <i>- stucco overlap of shingle / Drop siding → recommend removal of poorly installed stucco → and replace/repair → restore wood siding</i>					
SIDING/GRADE CLEARANCE <input checked="" type="checkbox"/> Maintain 6 - 8 inch clearance for proper protection of siding and framing		<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Soil/wood/concrete contact visible <input checked="" type="checkbox"/> Clear soil /wood /debris away from house and check for insect/rot damage
SOFFIT <input checked="" type="checkbox"/> See Sections 3.1 & 3.2 - Roofing & Attic <input checked="" type="checkbox"/> Wood / Stucco <input type="checkbox"/> Vinyl / Metal	<input type="checkbox"/> Open <input checked="" type="checkbox"/> Closed <input checked="" type="checkbox"/> With vents	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/> Cracked/damaged/stained/loose (see below) <input checked="" type="checkbox"/> Repair/replace soffits <input type="checkbox"/> Repair/replace vent screens
FASCIA/GABLE TRIM <input type="checkbox"/> Partially hidden by gutters	<input checked="" type="checkbox"/> Wood <input type="checkbox"/> Metal	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Repair/replace <input checked="" type="checkbox"/> Loose / Weathered / rot damage (see below)
OTHER TRIM <input checked="" type="checkbox"/> Wood / Metal / Vinyl <input type="checkbox"/> Window <input checked="" type="checkbox"/> Door <input type="checkbox"/> Shutters	<input checked="" type="checkbox"/> Horizontal <input checked="" type="checkbox"/> Vertical	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/> Repair/replace <input checked="" type="checkbox"/> Rot damage <input checked="" type="checkbox"/> Missing/loose <input checked="" type="checkbox"/> Weathered (see below)
FLASHING/CAULKING <input checked="" type="checkbox"/> Windows <input type="checkbox"/> Doors	<input type="checkbox"/> Base <input type="checkbox"/> Horizontal	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Flashing missing over doors/windows <input type="checkbox"/> Caulking required (regular maintenance) <input type="checkbox"/> Excessive caulking observed
<i>→ Prevents moisture intrusion @ exterior walls</i>					
PAINTED FINISHES <input type="checkbox"/> Siding / trim <input type="checkbox"/> Soffits/fascia <input type="checkbox"/> Decks / porches	<input type="checkbox"/> Build-up noted <input type="checkbox"/> Touch-up required	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Chipping, peeling or flaking <input checked="" type="checkbox"/> Painting/staining required <input checked="" type="checkbox"/> Weathered (see below)
<input checked="" type="checkbox"/> Severely weathered wood siding/trim will require extensive ongoing maintenance and frequent painting/staining. <input checked="" type="checkbox"/> Soffit stains may indicate roof leaks / condensation - obtain history from vendor <input checked="" type="checkbox"/> Inadequate soffit ventilation - install/increase soffit ventilation <input checked="" type="checkbox"/> Repairs/replacement required.					
<i>→ global approach to repairs needed</i> <i>- inadequate Flashing details @ West / East walls etc. causing moisture issues</i>					
GAS METER <input type="checkbox"/> Too close to electrical equipment <input type="checkbox"/> Too close to air intake		<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Gas leak - CONTACT GAS COMPANY <input type="checkbox"/> Add guard to protect from vehicles
Main Gas Shut-Off Valve located at: <input type="checkbox"/> Main Gas Meter <input type="checkbox"/> Mechanical Room OR Other _____					

2.2 EXTERIOR DOORS & WINDOWS

1 2 3

REF # 2016-102

◆ We do not guarantee detection of leaking thermal pane seals at windows/skylights/sliding doors, due to lighting variation or other atmospheric conditions. Consult a window specialist for further testing/evaluation.

WINDOWS

☒ Wood

☐ Aluminum

☐ Vinyl

☐ Glass blocks

☐ Some window upgrading

☐ Solarium (see section 2.5)

☒ Fixed / Casement

☒ Sliding / Awning

☐ Single/ Double-hung

☐ Hopper

☐ Cannot confirm tempered glass @

☐ Single glazing

☒ Double glazing

☐ Triple glazing

☐ Screens

☐ Storm windows

☐ Interior

☐ Exterior

☒ ☐ ☐

☐ Damaged sills/returns/sashes/muntins

☐ Evidence of condensation/leakage

☐ Broken/missing latches/handles/cranks

☐ Inoperative/painted shut

☐ Cracked/broken glass

☐ Evidence of failed seals

☐ Missing/damaged screens/storms

☐ Repair / replace

☐ SAFETY HAZARD: ☐ No quick release mechanism on bedroom security bars ☐ Floor to ceiling windows should be tempered.

☐ Window too small / inoperable / required in bedroom for emergency egress @

EXTERIOR DOORS

1. MAIN ENTRY

☐ Wood

☐ Solid core

☐ Hollow core

☐ Panel

☒ Metal

☒ Deadbolt lockset

☐ Door viewer

☐ With glazing

☐ Screen/storm door

☐ With side lite(s)

☒ ☐ ☐

☐ Moisture/rot damage

☐ Replace / install weather stripping

☐ Add deadbolt lockset

☐ Adjust/replace hardware

☐ Repair/replace/refinish/adjust door

☐ Change key-in lockset to thumb turn type

2. SIDE/REAR ENTRY @

Double door

☐ Wood

☐ Solid core

☐ Hollow core

☐ Panel

☒ Metal

☐ Deadbolt lockset

☐ Door viewer

☐ With glazing

☐ Screen/storm door

☐ French style

☒ ☐ ☐

☐ Moisture/rot damage

☐ Replace / install weather stripping

☐ Add deadbolt lockset

☐ Adjust/replace hardware

☐ Repair/replace/refinish/adjust door

☐ Change key-in lockset to thumb turn type

3. OTHER DOOR @

Kitchen

☒ Wood

☐ Solid core

☐ Hollow core

☐ Panel

☐ Metal

☐ Deadbolt lockset

☐ Door viewer

☐ With glazing

☐ Screen/storm door

☐ French style

☐ ☐ ☒

☒ Moisture/rot damage

☐ Replace / install weather stripping

☐ Add deadbolt lockset

☐ Adjust/replace hardware

☒ Repair/replace/refinish/adjust door

☐ Change key-in lockset to thumb turn type

4. OTHER DOOR @

☐ Wood

☐ Solid core

☐ Hollow core

☐ Panel

☐ Metal

☐ Deadbolt lockset

☐ Door viewer

☐ With glazing

☐ Screen/storm door

☐ French style

☐ ☐ ☐

☐ Moisture/rot damage

☐ Replace / install weather stripping

☐ Add deadbolt lockset

☐ Adjust/replace hardware

☐ Repair/replace/refinish/adjust door

☐ Change key-in lockset to thumb turn type

☐ Replace exterior hollow core / panel type doors with steel or solid wood doors.

1. SLIDING DOOR @

☐ Wood

☐ Aluminum

☐ Vinyl clad

☐ With lockset / deadbolt

☐ Single glazing

☐ Double glazing

☐ Triple glazing

☐ ☐ ☐

☐ Glass possibly not tempered

☐ Replace / install weather stripping

☐ Repair/replace hardware / lockset / door

☐ Evidence of failed seal

☐ Track/rollers need cleaning/repair

2. SLIDING DOOR @

☐ Wood

☐ Aluminum

☐ Vinyl clad

☐ With lockset / deadbolt

☐ Single glazing

☐ Double glazing

☐ Triple glazing

☐ ☐ ☐

☐ Glass possibly not tempered

☐ Replace / install weather stripping

☐ Repair/replace hardware / lockset / door

☐ Evidence of failed seal

☐ Track/rollers need cleaning/repair

3. SLIDING DOOR @

☐ Wood

☐ Aluminum

☐ Vinyl clad

☐ With lockset / deadbolt

☐ Single glazing

☐ Double glazing

☐ Triple glazing

☐ ☐ ☐

☐ Glass possibly not tempered

☐ Replace / install weather stripping

☐ Repair/replace hardware / lockset / door

☐ Evidence of failed seal

☐ Track/rollers need cleaning/repair

RATING

1) Functional/Satisfactory

2) Minor repairs/Maintenance Required

3) Poor/Unsatisfactory

2.3 PORCHES & DECKS

1 2 3

REF # 2016-02

- ◆ Deficiencies noted in this section may result in personal injury if not addressed.
- ◆ Type "S" roll roofing recommended between wood & concrete supports.
- ◆ Rail height should be a minimum of 36" where falls of 24" up to 72" exist.
- ◆ Rail height should be a minimum of 42" where falls exceeds 72"
- ◆ Openings through all vertical rails should be maximum 4"

- ◆ Seal wood surfaces periodically to extend life.
- ◆ Where wood/soil contact occurs: Check area for rot/insect damage & replace component(s) as necessary.
- ◆ We cannot confirm that the railing's glass inserts are tempered.

PORCH/DECK STRUCTURE

Front (main)

- ☐ Deck too low/covered - unable to inspect structure
- ☐ Footings not visible

- ☒ Concrete
- ☒ Wood
- ☐ Pressure treated
- ☐ Painted/stained

- ☐ With deck drain
- ☐ With gutters

- ☐ Over carport/garage
- ☐ Over living space
- ☐ Over storage area
- ☐ Screened
- ☐ Enclosed

- ☐ Piers
- ☒ Posts

- ☒ Beams
- ☒ Joists

RAILS & TRIM

- ☐ Open, no rail

- ☒ Wood
- ☐ Metal
- ☐ Glass/plastic inserts (see above)
- ☐ Wood frame - wood/stucco/vinyl/alum siding

STEPS & FLOORING

- ☐ Surface covered - unable to inspect membrane/decking
- ☐ Uneven steps

- ☒ Wood/plywood
- ☒ Concrete
- ☐ Fibreglass
- ☐ Vinyl / Carpet
- ☐ Waterproof coating

- ☐ Add anti-skid strips
- ☐ Trip hazard at steps / flooring

ROOF

- ☒ Part of main building roof (see Section 3.1 and 3.2 Roof and Attic)

- ☐ Fibreglass
- ☐ Metal
- ☐ Glass
- ☐ Canvas/vinyl
- ☒ MBR

- STRUCTURE:
- ☐ Wood
- ☐ Open trellis
- ☐ Metal

- ☐ Add ventilation at rail/floor

PORCH/DECK STRUCTURE

Side wall

- ☐ With hot tub
- ☐ Deck too low/covered - unable to inspect structure
- ☐ Footings not visible

- ☒ Concrete
- ☒ Wood
- ☒ Pressure treated
- ☒ Painted/stained

- ☐ With deck drain
- ☐ With gutters

- ☐ Over carport/garage
- ☐ Over living space
- ☐ Over storage area
- ☐ Screened
- ☐ Enclosed

- ☐ Piers
- ☐ Posts

- ☐ Beams
- ☐ Joists

RAILS & TRIM

- ☒ Open, no rail

- ☐ Wood
- ☐ Metal
- ☐ Glass/plastic inserts (see above)
- ☐ Wood frame - wood/stucco/vinyl/alum siding

STEPS & FLOORING

- ☐ Surface covered - unable to inspect membrane/decking
- ☐ Uneven steps

- ☒ Wood/plywood
- ☐ Concrete
- ☐ Fibreglass
- ☐ Vinyl / Carpet
- ☐ Waterproof coating

- ☐ Add anti-skid strips
- ☐ Trip hazard at steps / flooring

- ☐ Add ventilation at rail/floor

2.4 BALCONIES

1 2 3

REF # 2016-102

- ◆ **CONDOMINIUMS:** Many strata complexes have experienced major problems with at balconies. Refer to Strata Council Minutes for evidence of any related problems and for references to past and/or future repairs or replacement. Detailed inspection of these items is beyond the scope of this survey.
- Some/many balconies in complex have stucco cracks/stains - may be indication of major leaking/rot problems. **Further investigation required.**
- Evidence of recent repairs to balconies - Obtain copies of building envelope survey / engineer's report.
- ◆ We cannot confirm that the railing's glass inserts are tempered.
- ◆ Rail too low/openings too wide - improve to safer standard of 36" / 42" high with 4" max. openings between vertical railings

BALCONY # 1 @ <input type="checkbox"/> Wood <input type="checkbox"/> Concrete <input type="checkbox"/> Drain blocked/missing / not visible <input type="checkbox"/> Structure not visible	<input type="checkbox"/> Over living space <input type="checkbox"/> Screened <input type="checkbox"/> Enclosed <input type="checkbox"/> Solarium - (see Section 2.5)	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	<input type="checkbox"/> Repair/replace <input type="checkbox"/> Improper slope <input type="checkbox"/> Inadequate framing <input type="checkbox"/> Possible leaks/rot/moisture damage
RAILS & TRIM <input type="checkbox"/> Wood <input type="checkbox"/> Metal <input type="checkbox"/> Glass/plastic inserts (see above) <input type="checkbox"/> Wood frame - wood/stucco/vinyl/alum siding	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Repair/replace rails <input type="checkbox"/> Rails loose/improper attachment to building <input type="checkbox"/> Possible leaks/rot/moisture damage <input type="checkbox"/> Rail too low/openings too wide (see above)	
VENTILATION <input type="checkbox"/> Rails <input type="checkbox"/> Floor	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Provide ventilation at rail / floor <input type="checkbox"/> Install flashing at deck joint to exterior wall	
FLOORING <input type="checkbox"/> Wood <input type="checkbox"/> Concrete/pavers <input type="checkbox"/> Waterproof coating	<input type="checkbox"/> Vinyl <input type="checkbox"/> Carpet <input type="checkbox"/> Fibreglass	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Repair/replace <input type="checkbox"/> Poor drainage <input type="checkbox"/> Surface covered - unable to inspect
BALCONY # 2 @ <input type="checkbox"/> Wood <input type="checkbox"/> Concrete <input type="checkbox"/> Drain blocked/missing / not visible <input type="checkbox"/> Structure not visible	<input type="checkbox"/> Over living space <input type="checkbox"/> Screened <input type="checkbox"/> Enclosed <input type="checkbox"/> Solarium - (see Section 2.5)	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	<input type="checkbox"/> Repair/replace <input type="checkbox"/> Improper slope <input type="checkbox"/> Inadequate framing <input type="checkbox"/> Possible leaks/rot/moisture damage
RAILS & TRIM <input type="checkbox"/> Wood <input type="checkbox"/> Metal <input type="checkbox"/> Glass/plastic inserts (see above) <input type="checkbox"/> Wood frame - wood/stucco/vinyl/alum siding	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Repair/replace rails <input type="checkbox"/> Rails loose/improper attachment to building <input type="checkbox"/> Possible leaks/rot/moisture damage <input type="checkbox"/> Rail too low/openings too wide (see above)	
VENTILATION <input type="checkbox"/> Rails <input type="checkbox"/> Floor	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Provide ventilation at rail / floor <input type="checkbox"/> Install flashing at deck joint to exterior wall	
FLOORING <input type="checkbox"/> Wood <input type="checkbox"/> Concrete/pavers <input type="checkbox"/> Waterproof coating	<input type="checkbox"/> Vinyl <input type="checkbox"/> Carpet <input type="checkbox"/> Fibreglass	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Repair/replace <input type="checkbox"/> Poor drainage <input type="checkbox"/> Surface covered - unable to inspect
BALCONY # 3 @ <input type="checkbox"/> Wood <input type="checkbox"/> Concrete <input type="checkbox"/> Drain blocked/missing / not visible <input type="checkbox"/> Structure not visible	<input type="checkbox"/> Over living space <input type="checkbox"/> Screened <input type="checkbox"/> Enclosed <input type="checkbox"/> Solarium - (see Section 2.5)	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Repair/replace <input type="checkbox"/> Improper slope <input type="checkbox"/> Inadequate framing <input type="checkbox"/> Possible leaks/rot/moisture damage
RAILS & TRIM <input type="checkbox"/> Wood <input type="checkbox"/> Metal <input type="checkbox"/> Glass/plastic inserts (see above) <input type="checkbox"/> Wood frame - wood/stucco/vinyl/alum siding	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Repair/replace rails <input type="checkbox"/> Rails loose/improper attachment to building <input type="checkbox"/> Possible leaks/rot/moisture damage <input type="checkbox"/> Rail too low/openings too wide (see above)	
VENTILATION <input type="checkbox"/> Rails <input type="checkbox"/> Floor	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Provide ventilation at rail / floor <input type="checkbox"/> Install flashing at deck joint to exterior wall	
FLOORING <input type="checkbox"/> Wood <input type="checkbox"/> Concrete/pavers <input type="checkbox"/> Waterproof coating	<input type="checkbox"/> Vinyl <input type="checkbox"/> Carpet <input type="checkbox"/> Fibreglass	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Repair/replace <input type="checkbox"/> Poor drainage <input type="checkbox"/> Surface covered - unable to inspect

2.5 SOLARIUM(S), PATIO(S) & ELEVATED WALKWAY(S)

1 2 3

REF #

2016-102

♦ **CONDOMINIUMS:** Many strata complexes have experienced major problems with leaking patios, enclosed balconies/solariums and exposed elevated walkways. Refer to Strata Council Minutes for evidence of any related problems and for references to past and/or future repairs or replacement. Detailed inspection of these items is beyond the scope of this survey.

☐ Evidence of recent repairs to patio(s) and/or elevated walkway(s) - Obtain copies of building envelope survey / engineer's report.

SOLARIUM(S)

- ☐ Built on former deck/patio
☐ Enclosed balcony (See Section 2.4)

- ☐ Wood
☐ Aluminum
☐ Vinyl

- ☐ Single glazing
☐ Double glazing
☐ Plastic glazing



- ☐ Cracked/broken glazing
☐ Leaking/moisture damage
☐ Evidence of failed seals
☐ Glass possibly not tempered
☐ Interior staining indicative of previous leaks

PATIO(S)

- ☐ Planters
☐ With hot tub
☐ Central courtyard
☐ With pool/pond/fountain

- ☐ Concrete
☐ Brick/paver
☐ Stone
☐ With drain

- ☐ Settled/heaved
☐ Trip hazard
☐ Improper slope
☐ Drain blocked
☐ Drain missing/not visible



- ☐ Patio over living area/underground garage
☐ Damaged/missing wood spacers
☐ Re-grout joints/reset loose elements
☐ Surface covered - unable to inspect membrane
☐ Possible membrane failure over ceiling slab
☐ **EXTENSIVE REPAIRS MAY BE REQUIRED.**

PATIO COVER

- ☐ N/A
☐ Part of main roofing (See Section 3.1)

- ☐ Metal
☐ Fiberglass
☐ Glass/plastic
☐ Canvas/vinyl
☐ Open trellis

- STRUCTURE:**
☐ Metal
☐ Wood
☐ Retracting awning



- ☐ Improper attachment to house
☐ Rot/moisture damage
☐ Weathered/mildew/moss/algae
☐ Repair/replace
☐ Do not allow snow to accumulate

ELEVATED WALKWAY(S)

- ☐ Wood
☐ Concrete

- ☐ Exposed
☐ Enclosed/protected



- ☐ Cracks/stains observed—indication of possible major leaking/rot problem. **FURTHER INVESTIGATION REQUIRED.**

RAILS & TRIM

- ☐ With rails
☐ Open, no rail

- ☐ Wood
☐ Metal
☐ Wood frame - wood/stucco/vinyl/alum siding



- ☐ Provide/repair rails
☐ Rails loose/improper attachment to building
☐ Possible leaks/rot/moisture damage
☐ Rail too low/openings too wide (see below)

VENTILATION

- ☐ Rails

- ☐ Floor



- ☐ Provide ventilation at rail/floor

STEPS & FLOORING

- ☐ Surface covered - unable to inspect decking

- ☐ Wood
☐ Concrete
☐ Waterproof coating

- ☐ Vinyl
☐ Carpet
☐ Fibreglass



- ☐ Repair/replace
☐ Uneven steps
☐ Add anti-skid strips

♦ Rail height should be 31-38" high at steps & 42" high at landings. Openings through rails should be maximum 4".

RATING

1) Functional/Satisfactory

2) Minor repairs/Maintenance Required

3) Poor/Unsatisfactory

3.1 ROOFING - Page 1

1 2 3

REF # 2016-102

ROOF ACCESSIBILITY

♦ Refer to Section 3.2 - Attic for details on roof structure, roof sheathing, attic area, insulation etc.

☐ ACCESSIBLE
☒ PARTIALLY INSPECTED

ROOF VIEWED *of shed roof only*
☒ On roof / From edges of roof
☐ From windows / From balconies
☒ From ground with binoculars

☐ NOT ACCESSIBLE

LIMITATIONS / ACCESS RESTRICTED DUE TO:

☐ Roofing material fragile
☒ Building height / Steepness of roof
☐ Debris/moss / Wet and slippery
☐ Snow cover/frost/ice limits inspection to random spot checks
☐ Wood deck over roofing material

ROOF STYLE

☒ Approx. pitch (slope) *12/12*

☒ Flat
☒ Gable
☐ Hip
☐ Mansard

☒ Shed
☐ Gambrel
☐ A-frame

☒ Flat
☒ Low slope
☐ Medium slope
☒ Steep slope

metal roof

ROOFING MATERIAL

♦ See next page for roof condition details

☐ Asphalt shingles
☐ Wood
☐ Tile
☒ Metal

☐ BUR
☒ MBR
☐ EPDM
☐ PVC
☐ Roll

☐

☐ Apparent substandard material quality
☒ Inappropriate use of material
☒ Apparent improper/amateur installation
☒ Repairable/maintenance required
☒ Replacement recommended
☒ Evidence of recent repairs
☐ Prematurely aged
☒ Leaks noted

MBR - repairs needed

UNDERLAYMENT

☐ Eave protection

☐ Tar felts / Rosin
☐ Self-adhering
☐ Poly / Foil

☐

☒ None / not visible / only partially visible
☐ Visible at edges only
☐ Ripped/damaged foil

INTERLAYMENT

VALLEYS

☐ Open / Closed

☐ EPDM / MBR
☐ Metal flashing

☐ Woven shingles
☐ Cut shingles

☐

☐ Clean debris out of valleys
☐ Clean rust, repaint
☐ Apparent improper/amateur installation

N/A

FLASHING

♦ Recommend annual caulking & maintenance

☒ Plumbing vents
☐ Chimneys
☒ Walls
☒ Roof edges
☐ Skylights
☐ Electrical mast
☐ Dormers

☒ Aluminum
☒ Pre-finished
☒ Galvanized
☒ EPDM
☐ Painted
☐ Mastie
☐ Lead

☐

☐ Aging, corrosion/deterioration noted
☒ Membrane flashing need repairs
☒ Flashing loose/uplifted/missing
☐ Exposed nail heads
☐ Unsealed joints at perimeter flashing
☐ Improperly sloped at parapet/gravel stop
☐ Improper/missing flashing at skylights

☒ Install drip edge flashing to help protect fascia board/roof sheathing and divert roof drainage into gutters

☐ Flashing was not replaced when roof replaced

*→ Poor design - recommend to redo or alter @ MBR -> Roof of Front Porch
↳ Flashing installed Backwards*

GUTTERS

☐ None

☐ Aluminum
☐ Galvanized
☐ Plastic / Wood
☐ EPDM / Hidden

☐ Missing - add new

☐

☒ Damaged/loose/sagging / corrosion noted
☐ Drains plugged - Cleaning required
☐ Discharges onto roof - Add downspout and extend to gutter below
☐ Evidence of leakage at seams
☐ Re-slope to drains

DOWNSPOUTS

☐ 2 1/2"
☐ 4"

☐ Aluminum / Plastic
☐ Galvanized

☐ Missing
☐ Add splash blocks

☐

☐ Damaged / corrosion noted
☐ Re-connect / re-secure / install
☐ Discharges onto roof - extend downspout to gutter below

♦ Gutters, roof drains and downspouts are not probed to determine excessive corrosion and are not tested for blockage, leakage or proper slope.
♦ Gutters, downspouts and leaders should be installed at all eaves to divert roof drainage away from building surfaces / foundation

*Continuous Aluminium Gutters needed @ all Eaves
have downspouts connected to leader -> that
extend 8' down slope to lowest point @ site.*

RATING

1) Functional/Satisfactory

2) Minor repairs/Maintenance Required

3) Poor/Unsatisfactory

3.1 ROOFING - Page 2

1 2 3

REF # 2016-102

ASPHALT SHINGLES

- ☐ 1 - 2 - 3 tab
- ☐ T-lock
- ☐ Laminated

- ☐ Curled/clawed/ridged
- ☐ Brittle/cracked
- ☐ Broken/missing shingles
- ☐ Surface granules wearing

- ☐ Exposed/protruding nails
- ☐ Moss, algae, lichens
- ☐ Telegraphing visible
- ☐ Maximum 2 layers of shingles recommended

WOOD

- ☐ Shingles
- ☐ Shakes

- ☐ Surface deterioration of wood
- ☐ Broken/loose/missing shingles/shakes
- ☐ Ridge cap shingles missing/loose

- ☐ Exposed/lifted nails
- ☐ Moss covered, rotted sections
- ☐ Crumbly butt ends

TILE

- ☐ Concrete
- ☐ Clay
- ☐ Slate

- ☐ Broken/cracked/chipped tiles
- ☐ Missing tiles
- ☐ Slipped tiles
- ☐ Bird-stop or eave closure missing
- ☐ Snow guards

- ☐ Inappropriate overlap (min. 3" required)
- ☐ Mastic cement between ridge tiles missing
- ☐ Cement mortar at ridge tiles missing
- ☐ Lead flashing missing

◆ Not all tiles are checked for attachment - limited inspection

METAL

- ☐ Shingles
- ☐ Interlocking panel
- ☒ Sheets

- ☐ With standing seams
- ☐ Soldered
- ☐ Snow guards
- ☐ Pre-coated
- ☒ Painted
- ☐ Unpainted

- ☒ Buckling (oil canning)
- ☐ Rusting / Requires painting
- ☒ Fasteners loose / missing
- ☐ Deteriorated finish

FLAT ROOFING

- ☐ Built-Up Roofing (BUR)
- ☒ Modified Bitumen Roofing (MBR)
- ☐ Synthetic rubber (EPDM)
- ☐ Thermoplastic (PVC)
- ☐ Roll

- ☐ Smooth
- ☐ Reflective coating
- ☒ Granular surface
- ☐ Gravel surface

- ☐ Perimeter flashing
- ☐ Parapet wall
- ☐ Scuppers/drains blocked - CLEAN
- ☐ Add strainer baskets

- ☐ Blistered/bubbled/buckled/ridged
- ☐ Alligatoring/cracking/punctures
- ☐ Exposed felts/delamination/fishmouths
- ☐ Powdery or flaky surfaces
- ☐ Open seams
- ☐ Slippage
- ☐ Bare spots
- ☒ Membrane flashing defects
- ☐ Ponded water (EXPECT ACCELERATED DETERIORATION)

see below *

◆ ROOFS CAN LEAK UNPREDICTABLY AND THE INSPECTOR DOES NOT ATTEMPT TO ESTIMATE THE REMAINING LIFE OF ROOFING MATERIALS - PLEASE NOTE THAT YEARLY MAINTENANCE AND REGULAR REPAIRS WILL BE REQUIRED.

- ☐ Roof appears to be installed to current industry practices but may not comply with CSA Standards and/or manufacturer's specifications
- ☐ Roof was not walked on to avoid causing damage
- ☒ Evidence of ice damming: provide eave protection/improve attic ventilation

- ☐ Clean debris off roof
- ☐ Remove/trim tree branches/vegetation
- ☐ Add zinc strips/pellets to control moss
- ☐ TV antenna does not appear to be grounded

- ☒ Obtain copy of receipts for recent roof repairs/replacement as warranties on labour/materials may be transferable.
- ☐ Laminated asphalt shingles / metal roofing / roll roofing not rated by manufacturer for use on low slopes/flat roofing
- ☐ Light gauge fiberglass roofing is temporary material. Budget to replace frequently. Located @ _____
- ☒ Recommend further investigation/repairs by a licensed roofing contractor
- ☒ Roof appears to be nearing/at end of useful life - BUDGET FOR REPLACEMENT.

◆ CONDOMINIUM INSPECTION: Review Strata Council Minutes for references to past and/or future repairs, replacement and maintenance information. Obtain copies of any engineering reports.

◆ This report is an opinion of the general quality and condition of the roofing materials at the time of inspection. The inspector cannot, and does not, offer a guarantee as to whether the roof has leaked in the past, leaks now, or may be subject to future leakage.

Gable / shed Roof systems → recommend to remove existing metal Roofs → and install Laminated asphalt shingles, Marley shingles

- recommend to re sheath entire Roof with plywood
- new Roof Flashings through out
- ice and weather shield where applicable

Flat Roof → @ Front entrance → Gutter rails have compromised MBR → leaks will occur. edge Flashing installed → repairs need. backwards → repair, replace

RATING

1) Functional/Satisfactory

2) Minor repairs/Maintenance Required

3) Poor/Unsatisfactory

3.1 ROOFING - Page 3

1 2 3

REF # 2016-102

CHIMNEY # 1

- ☐ Brick / Masonry block
☐ Metal / Framed chase

- ☐ Clay/masonry liner
☐ Metal liner
☐ Unlined

- ☐ Chimney cap
☐ Rain cap
☐ Clean-out

☐ ☐ ☒

- ☐ Settling / Leaning - bracing/repairs required
☐ Masonry repairs/repointing required
☐ Cracked/deteriorated/rusting
☐ See comments & recommendations below

CHIMNEY # 2

- ☐ Brick / Masonry block
☐ Metal / Framed chase

- ☐ Clay/masonry liner
☐ Metal liner
☐ Unlined

- ☐ Chimney cap
☐ Rain cap
☐ Clean-out

☐ ☐ ☐

- ☐ Settling / Leaning - bracing/repairs required
☐ Masonry repairs/repointing required
☐ Cracked/deteriorated/rusting
☐ See comments & recommendations below

CHIMNEY # 3

- ☐ Brick / Masonry block
☐ Metal / Framed chase

- ☐ Clay/masonry liner
☐ Metal liner
☐ Unlined

- ☐ Chimney cap
☐ Rain cap
☐ Clean-out

☐ ☐ ☐

- ☐ Settling / Leaning - bracing/repairs required
☐ Masonry repairs/repointing required
☐ Cracked/deteriorated/rusting
☐ See comments & recommendations below

◆ Interiors of chimneys and flues are not inspected.

☐ Chimney cap missing/broken @ Chimney # _____

☐ Add rain cap to flue @ Chimney # _____

☐ Flue cleaning & inspection by WETT certified technician is advised now @ Chimney # _____

☐ Insufficient roof clearance @ Chimney # _____

☐ Repair/replace flashing @ Chimney # _____

☐ Install metal liner @ Chimney # _____

SKYLIGHT # 1

- ☐ Bubble
☐ Opening type

- ☐ Glass
☐ Plastic
☐ Strip panel glazing

☐ ☐ ☐

- ☐ Cracked/damaged/defective
☐ Evidence of failed seal
☐ Evidence of leakage / condensation
☐ Apparent improper/amateur installation
☐ See comments & recommendations below

SKYLIGHT # 2

- ☐ Bubble
☐ Opening type

- ☐ Glass
☐ Plastic
☐ Strip panel glazing

☐ ☐ ☐

- ☐ Cracked/damaged/defective
☐ Evidence of failed seal
☐ Evidence of leakage / condensation
☐ Apparent improper/amateur installation
☐ See comments & recommendations below

SKYLIGHT # 3

- ☐ Bubble
☐ Opening type

- ☐ Glass
☐ Plastic
☐ Strip panel glazing

☐ ☐ ☐

- ☐ Cracked/damaged/defective
☐ Evidence of failed seal
☐ Evidence of leakage / condensation
☐ Apparent improper/amateur installation
☐ See comments & recommendations below

SKYLIGHT # 4

- ☐ Bubble
☐ Opening type

- ☐ Glass
☐ Plastic
☐ Strip panel glazing

☐ ☐ ☐

- ☐ Cracked/damaged/defective
☐ Evidence of failed seal
☐ Evidence of leakage / condensation
☐ Apparent improper/amateur installation
☐ See comments & recommendations below

◆ We do not guarantee detection of leaking thermal pane seals at skylights, due to lighting variation or other atmospheric conditions. Consult a window specialist for further testing/evaluation.

☐ Improper/missing flashing @ Skylight # _____

☐ Fasten frame to curb @ Skylight # _____

☐ Old skylight(s) should have been replaced when roof was replaced

☐ Replace old skylight(s) upon roof replacement

RATING

1) Functional/Satisfactory

2) Minor repairs/Maintenance Required

3) Poor/Unsatisfactory

3.2 ATTIC, VENTILATION AND INSULATION

1 2 3

REF #

2016-102

ATTIC	<input type="checkbox"/> No attic area	<input type="checkbox"/> Skylight wells <input checked="" type="checkbox"/> Multiple areas	<input type="checkbox"/> Dormer(s) <input checked="" type="checkbox"/> Half storey	<input type="checkbox"/> Vaulted or cathedral ceiling(s)
ATTIC ACCESS	<input checked="" type="checkbox"/> Ceiling hatch x3 <input type="checkbox"/> Stairs/pulldown <input type="checkbox"/> Garage hatch <input type="checkbox"/> Scuttle	Viewed from: <input checked="" type="checkbox"/> Hatch only <input checked="" type="checkbox"/> Traverse of attic	<input type="checkbox"/> No access - restricted due to: <input checked="" type="checkbox"/> Full evaluation not possible due to stored items / debris / limited access / fixed shelving.	
ATTIC FINISH	<input checked="" type="checkbox"/> Unfinished	<input type="checkbox"/> Partially finished	<input type="checkbox"/> Fully finished	
MECHANICAL/ELECTRICAL N.A	<input type="checkbox"/> Attic light		<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Plumbing / bath / kitchen fan vented into attic <input type="checkbox"/> Improper wiring <input type="checkbox"/> Insufficient clearance over recessed lights
FLOOR STRUCTURE/STORAGE AREA x None	<input type="checkbox"/> Full <input type="checkbox"/> Partial		<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Remove storage: structure not designed for additional weight <input type="checkbox"/> Open chases(s) should be sealed
ROOF STRUCTURE	<input type="checkbox"/> 2 X 4 on 24" O.C. <input type="checkbox"/> Not visible	<input type="checkbox"/> 2 X 4 on 16" O.C. <input type="checkbox"/> 2 X 6 on 16" O.C. <input checked="" type="checkbox"/> Engineered truss x2x	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	<input checked="" type="checkbox"/> Cracked/broken/sagging rafters <input type="checkbox"/> Ridge sagging <input checked="" type="checkbox"/> Truss damage/modification <input checked="" type="checkbox"/> Repairs recommended Primary attic
SECONDARY SUPPORTS	<input type="checkbox"/> Knee wall <input type="checkbox"/> Collar ties	<input type="checkbox"/> Lateral truss bracing	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	<input checked="" type="checkbox"/> Cracked/broken/loose bracing observed <input checked="" type="checkbox"/> Add bracing/support
ROOF SHEATHING	<input type="checkbox"/> Plywood <input type="checkbox"/> OSB <input type="checkbox"/> Particle board <input type="checkbox"/> With H-clips	<input checked="" type="checkbox"/> Shiplap <input type="checkbox"/> Strapping <input checked="" type="checkbox"/> 1 X board	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Mildew <input type="checkbox"/> Sheathing damaged <input checked="" type="checkbox"/> Leaks noted <input type="checkbox"/> Signs of condensation (see below) <input type="checkbox"/> Roof sheathing soft/spongy ledge North addition -> attic -> no ledger plate to support rafters. Plate needed
FIRE SEPARATION	<input checked="" type="checkbox"/> One hour fire-rated wall required between strata units. <input type="checkbox"/> None/not visible	<input type="checkbox"/> Gypsum wallboard	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> No fire separation - install <input type="checkbox"/> Holes/taping inadequate/missing - repair <input checked="" type="checkbox"/> Cannot confirm compliance to Fire Code
<p>♦ Recessed lights may not be approved for installation in contact with insulation.</p> <p>Ventilation of attic system recommended.</p> <p>- soffit vents required -> strip vents recommended</p> <p>- roof -> Box vents @ shed Roofs -> Gable vents/ridge v.c.</p>				
VENTILATION	<input type="checkbox"/> None	<input type="checkbox"/> Cont. soffit vents <input type="checkbox"/> Cont. ridge vents <input type="checkbox"/> Power attic ventilator <input type="checkbox"/> Turbine	<input type="checkbox"/> Soffit grills <input type="checkbox"/> Roof vents <input checked="" type="checkbox"/> Gable/dormer vents <input type="checkbox"/> Whole house fan	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> Attic ventilation improvement is advisable <input type="checkbox"/> Fan noisy or vibrates - repair <input checked="" type="checkbox"/> Add baffles between rafters/trusses @ soffit <input type="checkbox"/> Vent screens damaged/missing/blocked Gable Roof
INSULATION	<input type="checkbox"/> None Est. R-Value 20	<input checked="" type="checkbox"/> Batt <input type="checkbox"/> Blown/loose <input type="checkbox"/> Rigid foam	<input type="checkbox"/> Fiberglass <input checked="" type="checkbox"/> Cellulose <input type="checkbox"/> Mineral/rock wool <input checked="" type="checkbox"/> Vermiculite	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> Consider improving R-50 <input checked="" type="checkbox"/> Uneven distribution/partially installed <input type="checkbox"/> Insulate and weatherstrip attic hatch <input type="checkbox"/> Insulate exposed fan ducts
VAPOUR BARRIER	<input type="checkbox"/> None/not visible	<input type="checkbox"/> Poly	<input checked="" type="checkbox"/> Paper	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> seal penetrations through ceiling
WATER/MOISTURE EVIDENCE	<input type="checkbox"/> No evidence seen.		<input type="checkbox"/> Rust on nails <input checked="" type="checkbox"/> Water stains - wet/dry <input type="checkbox"/> Drip stains on rafters/insulation	<input checked="" type="checkbox"/> Evidence of past leakage <input type="checkbox"/> Active leaks observed <input type="checkbox"/> Condensation on interior finishes
PESTS	<input type="checkbox"/> No evidence seen	<input type="checkbox"/> Droppings visible <input type="checkbox"/> Damage visible	<input checked="" type="checkbox"/> Carpenter ants <input type="checkbox"/> Termites <input type="checkbox"/> Wasps/bees	<input type="checkbox"/> Birds <input type="checkbox"/> Rodents <input type="checkbox"/> Evidence of past / active infestation <input type="checkbox"/> Consult pest control company Red ants @ Primary attic @ West Gable -> no damage occurring

RATING

1) Functional/Satisfactory

2) Minor repairs/Maintenance Required

3) Poor/Unsatisfactory

4.1 WALLS/CEILINGS/FLOORS

1 2 3

REF # 2016-102

A. "Normal" hairline cracks may be due to slight seasonal movement of framing and/or minor settlement.

B. Excessive cracks indicate a past and possible active foundation movement; should be monitored and may require structural repairs or reinforcement.

WALLS

- ☒ Normal hairline cracks (see "A" above)
☐ Significant cracks. (see "B" above)

- ☒ Gypsum board
☐ Plaster
☐ Panelling
☐ Paint
☐ Wallpaper
☐ Mirror

☐ ☒ ☐

- ☐ Loose/cracked plaster
☐ Leaks/stains/mould (see below)
☒ Holes/mechanical damage
☐ Damaged/loose wallpaper
☐ Evidence of recent repairs/painting/patching

CEILINGS

- ☒ Flat
☒ Vaulted/open beam

- ☒ Gypsum board
☐ Plaster
☒ Wood
☐ Acoustic tile
☒ T-bar tile
☐ Textured

☐ ☒ ☐

- ☒ Normal hairline cracks (see "A" above)
☐ Significant cracks. (see "B" above)
☒ Loose/cracked plaster
☒ Leaks/stains/mould (see below)
☐ Evidence of recent repairs/painting/patching

FLOORS

- ☐ Water stains/moisture damage (see below)
☒ Uneven/sloped areas noted

- ☐ Hardwood
☒ Softwood
☐ Carpet over wood
☐ Carpet
☐ Ceramic
☒ Linoleum
☒ Vinyl/VA tile
☐ Cork
☐ Laminate
☐ Marble/stone/slate
☐ Concrete

☐ ☒ ☐

- ☐ Worn/stained/damaged carpet
☐ Worn/damaged vinyl tile/linoleum
☐ Broken/cracked ceramic/marble - repair grout
☒ Refinish wood floor
☐ Remove carpet from kitchen/bathroom

STAIRS

- From main*
☐ N/A to loft

- ☐ Carpet
☒ Wood
☐ Very steep
☐ Very narrow
☐ Loose treads
☐ Improper lighting
☐ Worn/torn carpet

☐ ☒ ☐

- ☐ Insufficient headroom
☐ Handrail missing/loose/too low
☒ Guardrail missing/loose/too low
☐ Rail openings too wide at handrail/guardrail
☐ Improper rise/run of steps: possible trip hazard

STAIRS

- ☐ N/A

- ☐ Carpet
☐ Wood
☐ Very steep
☐ Very narrow
☐ Loose treads
☐ Improper lighting
☐ Worn/torn carpet

☐ ☐ ☐

- ☐ Insufficient headroom
☐ Handrail missing/loose/too low
☐ Guardrail missing/loose/too low
☐ Rail openings too wide at handrail/guardrail
☐ Improper rise/run of steps: possible trip hazard

- A) Water stains @ *ceiling @ loft area*
B) Water stains @ *Bath - mens - toilet area*
C) Water stains @ _____
D) Water stains @ _____
E) Water stains @ _____

- ☒ Stains checked with moisture meter ☒ Dry ☐ Damp ☐ Wet
☒ Stains checked with moisture meter ☐ Dry ☒ Damp ☐ Wet
☐ Stains checked with moisture meter ☐ Dry ☐ Damp ☐ Wet
☐ Stains checked with moisture meter ☐ Dry ☐ Damp ☐ Wet
☐ Stains checked with moisture meter ☐ Dry ☐ Damp ☐ Wet

- ◆ Obtain explanation and/or history of all stains from the vendors.
◆ Wall cavities are not checked. THIS IS NOT A UFFI INSPECTION.
☐ Wood finishes may mask stains / moisture evidence @ walls / ceilings.

- ☒ Renovations done in a professional/amateur workmanship.
☐ Missing/loose/damaged wood trim.

- ◆ Homes built before 1980 may have components containing asbestos or lead. Testing required to confirm presence of these substances.
☐ Full inspection of walls & flooring prohibited by furnishings. Only the general condition of visible areas is reported.

*Keep stored items away from Electrical panels
accessibility needed*

INTERIOR DOORS

- ☐ Types matched

- ☐ Hollow core
☒ Solid core
☐ Panel
☐ French doors
☐ Pocket door

☒ ☐ ☐

- ☐ Cracked/broken glass
☐ Doors missing/damaged/misaligned
☐ Repair/adjust/replace hardware

CLOSET SPACE

- ☐ View of interior limited by stored items

☐ ☐ ☒

- ☐ Some rooms lack closet space

CLOSET DOORS

- ☐ Wood
☐ Mirrored
☐ Louvered
☐ Metal
☐ Bi-fold
☐ Sliding
☐ Hinged

☐ ☐ ☒

- ☐ Doors off tracks
☐ Doors missing/damaged
☐ Mirror broken/cracked
☐ Repair/adjust/replace hardware

- ☐ Undercut doors to rooms to allow for air circulation

RATING

1) Functional/Satisfactory

2) Minor repairs/Maintenance Required

3) Poor/Unsatisfactory

4.3 BATHROOMS			1	2	3	REF # 2016-102
BATHROOM # <u>#1</u>			LOCATION <u>mens bathroom</u>			
TUB/SHOWER ENCLOSURE <input type="checkbox"/> High moisture content in wall cavity (see below)	<input type="checkbox"/> Ceramic <input type="checkbox"/> Plastic <input type="checkbox"/> Metal <input type="checkbox"/> Fiberglass <input type="checkbox"/> Glass	<input type="checkbox"/> Rusted <input type="checkbox"/> Chipped <input type="checkbox"/> Caulking deteriorated / mould visible	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	<input type="checkbox"/> Repair/reset tiles, possible hidden damage <input type="checkbox"/> Replace caulk/grout <input type="checkbox"/> Seal tile grout with silicone spray <input type="checkbox"/> Glass enclosure possibly not tempered <input type="checkbox"/> Shower head / diverter leaks		
TUB <input type="checkbox"/> With shower	<input type="checkbox"/> Whirlpool <input type="checkbox"/> Clawfoot tub <input type="checkbox"/> Sunken	<input type="checkbox"/> Rusted <input type="checkbox"/> Chipped <input type="checkbox"/> Finish worn	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	<input type="checkbox"/> Drain stopper not operational / missing <input type="checkbox"/> Slow draining - trap may need cleaning <input type="checkbox"/> Whirlpool equipment not visible/not tested		
SINK(S) <input type="checkbox"/> Moisture evidence below sink tested dry/wet	<input type="checkbox"/> With vanity <input type="checkbox"/> Pedestal <input checked="" type="checkbox"/> Wall hung	<input type="checkbox"/> Rusted <input type="checkbox"/> Chipped <input type="checkbox"/> Cracked	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Sink drain stopper non-functional <input type="checkbox"/> Damage to cabinet / doors / countertop <input type="checkbox"/> Trap leaking/slow draining <input type="checkbox"/> Sink faucet leaks		
TOILET <input type="checkbox"/> Does not flush properly <input type="checkbox"/> Water runs continually in tank <input type="checkbox"/> Moisture around toilet <input checked="" type="checkbox"/> High moisture content in floor (see below) <u>medium</u>			<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Cracked tank/base/bowl/cover- replace <input type="checkbox"/> Loose at floor - reset on new wax seal & tighten floor bolts <input type="checkbox"/> Repair/replace valve/ballcock/flapper		
VENTILATION	<input type="checkbox"/> Window	<input checked="" type="checkbox"/> Fan	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Noisy/weak - Provide/replace exhaust fan		
ELECTRICAL <input checked="" type="checkbox"/> Lights <input checked="" type="checkbox"/> Heat source <input type="checkbox"/> Heat lamp	<input type="checkbox"/> Razor outlet only <input type="checkbox"/> Outlets <input type="checkbox"/> GFCI		<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Provide heat source <input checked="" type="checkbox"/> No outlets/plan to add <u>time</u> <input checked="" type="checkbox"/> Add GFCI outlet		
<input checked="" type="checkbox"/> Extent of water damage to wall cavity (floor components) cannot be determined without removal of tiles/tub surround and wallboard (toilet and some flooring). Replacement of all components may be necessary. <input type="checkbox"/> Sterilize and clean whirlpool tub before use and regularly thereafter						
BATHROOM # <u>#2</u>			LOCATION <u>womens bathroom</u>			
TUB/SHOWER ENCLOSURE <input type="checkbox"/> High moisture content in wall cavity (see below)	<input type="checkbox"/> Ceramic <input type="checkbox"/> Plastic <input type="checkbox"/> Metal <input type="checkbox"/> Fiberglass <input type="checkbox"/> Glass	<input type="checkbox"/> Rusted <input type="checkbox"/> Chipped <input type="checkbox"/> Caulking deteriorated / mould visible	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	<input type="checkbox"/> Repair/reset tiles, possible hidden damage <input type="checkbox"/> Replace caulk/grout <input type="checkbox"/> Seal tile grout with silicone spray <input type="checkbox"/> Glass enclosure possibly not tempered <input type="checkbox"/> Shower head / diverter leaks		
TUB <input type="checkbox"/> With shower	<input type="checkbox"/> Whirlpool <input type="checkbox"/> Clawfoot tub <input type="checkbox"/> Sunken	<input type="checkbox"/> Rusted <input type="checkbox"/> Chipped <input type="checkbox"/> Finish worn	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	<input type="checkbox"/> Drain stopper not operational / missing <input type="checkbox"/> Slow draining - trap may need cleaning <input type="checkbox"/> Whirlpool equipment not visible/not tested		
SINK(S) <input type="checkbox"/> Moisture evidence below sink tested dry/wet	<input type="checkbox"/> With vanity <input type="checkbox"/> Pedestal <input checked="" type="checkbox"/> Wall hung	<input type="checkbox"/> Rusted <input type="checkbox"/> Chipped <input type="checkbox"/> Cracked	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Sink drain stopper non-functional <input type="checkbox"/> Damage to cabinet / doors / countertop <input type="checkbox"/> Trap leaking/slow draining <input type="checkbox"/> Sink faucet leaks		
TOILET <u>K2</u> <input type="checkbox"/> Does not flush properly <input type="checkbox"/> Water runs continually in tank <input type="checkbox"/> Moisture around toilet <input type="checkbox"/> High moisture content in floor (see below)			<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Cracked tank/base/bowl/cover- replace <input type="checkbox"/> Loose at floor - reset on new wax seal & tighten floor bolts <input type="checkbox"/> Repair/replace valve/ballcock/flapper		
VENTILATION	<input type="checkbox"/> Window	<input checked="" type="checkbox"/> Fan	<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Noisy/weak - Provide/replace exhaust fan		
ELECTRICAL <input checked="" type="checkbox"/> Lights <input checked="" type="checkbox"/> Heat source <input type="checkbox"/> Heat lamp	<input type="checkbox"/> Razor outlet only <input type="checkbox"/> Outlets <input type="checkbox"/> GFCI		<input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Provide heat source <u>upgrade</u> <input checked="" type="checkbox"/> No outlets/plan to add <u>current</u> <input checked="" type="checkbox"/> Add GFCI outlet <u>electric heat</u>		
<input type="checkbox"/> Extent of water damage to wall cavity (floor components) cannot be determined without removal of tiles/tub surround and wallboard (toilet and some flooring). Replacement of all components may be necessary. <input type="checkbox"/> Sterilize and clean whirlpool tub before use and regularly thereafter						

4.2 KITCHEN			1	2	3	REF # 2016-102
CABINETS <input type="checkbox"/> Cabinets damaged	<input checked="" type="checkbox"/> Wood/plywood <input type="checkbox"/> Particle board/MDF <input type="checkbox"/> Metal	<input type="checkbox"/> Plastic laminate <input type="checkbox"/> Melamine <input type="checkbox"/> Lacquer	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Missing handles <input type="checkbox"/> Adjust hinges <input checked="" type="checkbox"/> Repair/replace/refinish
COUNTER <input type="checkbox"/> View of counter restricted by dishes/appliances	<input checked="" type="checkbox"/> Plastic laminate <input type="checkbox"/> Wood <input type="checkbox"/> Marble/granite/slate	<input type="checkbox"/> Ceramic <input type="checkbox"/> Corian type <input type="checkbox"/> _____	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/> Slight damage/cuts & scratches <input checked="" type="checkbox"/> Seal counter to backsplash <input checked="" type="checkbox"/> De-laminating
FLOOR COVERING <input checked="" type="checkbox"/> Uneven/sloped areas	<input type="checkbox"/> Wood <input type="checkbox"/> Vinyl/VA tile <input type="checkbox"/> Cork	<input type="checkbox"/> Ceramic <input checked="" type="checkbox"/> Linoleum <input type="checkbox"/> _____	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Worn/stained/damaged <input type="checkbox"/> Curling at edges <input type="checkbox"/> Broken/cracked ceramic/marble - repair grout
WALL COVERING	<input type="checkbox"/> Plaster <input checked="" type="checkbox"/> Gypsum wallboard <input type="checkbox"/> Paper/panelling	<input type="checkbox"/> Ceramic <input type="checkbox"/> Combo <input type="checkbox"/> _____	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Possible hidden water damage <input type="checkbox"/> Further investigation required
SINK	<input type="checkbox"/> 1-Basin <input type="checkbox"/> 1 1/2 Basin <input checked="" type="checkbox"/> 2-Basin X2	<input checked="" type="checkbox"/> Stainless steel <input type="checkbox"/> Porcelain <input type="checkbox"/> Acrylic <input type="checkbox"/> _____	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Minor chips, scratches or damage <input type="checkbox"/> Caulk around edges <input checked="" type="checkbox"/> Moisture evidence below sink tested dry/wet <input type="checkbox"/> Slow draining
FAUCET/TRAP/DRAIN	<input type="checkbox"/> Sprayer <input type="checkbox"/> Tested functional <input type="checkbox"/> Not functional /leaking		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/> Trap deteriorated/leaks X1 <input type="checkbox"/> Improper trap - consult plumber <input type="checkbox"/> Faucet leaks
ELECTRIC OUTLETS	<input type="checkbox"/> 2 - Prong <input checked="" type="checkbox"/> 3 - Prong	<input type="checkbox"/> GFCI <input checked="" type="checkbox"/> Grounded	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Additional outlets advised <input type="checkbox"/> Reverse polarity / open ground <input checked="" type="checkbox"/> Add GFCI outlets
EXHAUST FAN	Brand _____ <input checked="" type="checkbox"/> Vented to exterior <input type="checkbox"/> Recirculating fan <input type="checkbox"/> Downdraft	<input type="checkbox"/> With microwave <input type="checkbox"/> With charcoal filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> No fan - plan to install <input type="checkbox"/> Vent fan to exterior <input type="checkbox"/> Fan needs cleaning <input type="checkbox"/> Supply charcoal filter <input type="checkbox"/> Weak or poor condition blower motor
♦ High volume exhaust fans require make-up air supply _____ _____ _____						
APPLIANCES						
Appliances are not moved. Testing of appliances is not part of this inspection. Obtain warranty and instruction booklets for all appliances.						
DISPOSAL <input type="checkbox"/> None	Brand _____	<input type="checkbox"/> Blades not checked <input type="checkbox"/> Jammed or does not operate <input type="checkbox"/> Unit is noisy/vibrates				
DISHWASHER <input type="checkbox"/> None/not included	Brand _____	<input type="checkbox"/> Built-in <input type="checkbox"/> Portable				<input type="checkbox"/> Chipped/rusted interior finish <input type="checkbox"/> Deteriorated seal <input type="checkbox"/> Door spring needs adjustment/repair
RANGE/OVEN <input type="checkbox"/> None/not included	Brand _____	<input type="checkbox"/> Gas <input type="checkbox"/> Electric				<input type="checkbox"/> Burners won't light <input type="checkbox"/> Door spring needs adjustment/repair
COOKTOP <input type="checkbox"/> None/not included	Brand _____	<input type="checkbox"/> Gas <input type="checkbox"/> Electric				<input type="checkbox"/> Burners won't light
MICROWAVE <input type="checkbox"/> None/not included	Brand _____	<input type="checkbox"/> With fan <input type="checkbox"/> Free-standing <input type="checkbox"/> Built-in				
REFRIGERATOR <input type="checkbox"/> None/not included	Brand _____	<input type="checkbox"/> Frost-free <input type="checkbox"/> Ice maker				<input type="checkbox"/> Ice maker not checked <input type="checkbox"/> Door seal deteriorated
<input type="checkbox"/> OTHER _____						

RATING

1) Functional/Satisfactory

2) Minor repairs/Maintenance Required

3) Poor/Unsatisfactory

4.4 LAUNDRY FACILITIES

1 2 3

REF # 2016-102

♦ Testing of appliances is not part of this inspection. Obtain warranty cards and instruction booklets for all appliances included.

LOCATION	<input type="checkbox"/> Basement	<input type="checkbox"/> Utility Area	<input type="checkbox"/> Garage	<input type="checkbox"/> Other _____
WASHING MACHINE	Brand _____	<input type="checkbox"/> Not included	<input type="checkbox"/> 120V outlet polarity reversed: Repair ASAP <input type="checkbox"/> Separate 120V grounded circuit required <input type="checkbox"/> Outlet inaccessible - not tested	
WASHER DRAINAGE	<input type="checkbox"/> Not visible	<input type="checkbox"/> Stand pipe <input type="checkbox"/> Laundry tub	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Floor drain <input type="checkbox"/> Improper trap
WASHER SUPPLY	<input type="checkbox"/> Recessed in wall <input type="checkbox"/> Not visible	<input type="checkbox"/> With laundry tub <input type="checkbox"/> Hot/cold drops on wall	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Leaky supply valves <input type="checkbox"/> Re-secure drops to wall <input type="checkbox"/> Recessed in wall - not visible
CLOTHES DRYER	Brand _____	<input type="checkbox"/> Not included	<input type="checkbox"/> 120/240V outlet inaccessible: not tested <input type="checkbox"/> Electric <input type="checkbox"/> Gas <input type="checkbox"/> Hard-wired - install outlet	
DRYER FACILITIES	<input type="checkbox"/> Exterior dryer vent <input type="checkbox"/> Not visible	<input type="checkbox"/> Gas available/close <input type="checkbox"/> No dryer vent	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Install exterior dryer vent <input type="checkbox"/> Flex duct detached/damaged <input type="checkbox"/> Replace duct with foil or metal duct
UTILITY/LAUNDRY SINK/TUB	<input type="checkbox"/> Plastic <input type="checkbox"/> Fibreglass <input type="checkbox"/> None	<input type="checkbox"/> Concrete <input type="checkbox"/> Porcelain <input type="checkbox"/> Stainless steel <input type="checkbox"/> Other _____	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Secure tub to wall or floor <input type="checkbox"/> Cracked/chipped <input type="checkbox"/> Improper/leaking trap/drain <input type="checkbox"/> Faucet leaks
CENTRAL VACUUM	Brand _____	<input type="checkbox"/> Rough-in only	<input type="checkbox"/> Extend exhaust to exterior <input type="checkbox"/> Accessories not tested	
<input type="checkbox"/> N/A Located @ _____				

4.5 VENTILATION AND CONDENSATION

- ♦ Condensation of moisture on windows or other cold surfaces should be controlled. Excessive moisture can cause nuisance staining of window frames and wall finishes, growth of mould and mildew, and can lead to serious structural damage. Generally, improved control of condensation can be achieved by increasing ventilation and reducing moisture.
- ♦ Some moulds can be highly toxic and hazardous to health. Testing is required to determine the level of toxicity.
- ♦ Indoor Air Quality Assessment is beyond the scope of this inspection.

SIGNS OF MOISTURE/CONDENSATION	<input type="checkbox"/> None observed	<input checked="" type="checkbox"/> Mould/mildew <input checked="" type="checkbox"/> Damp areas <input checked="" type="checkbox"/> Attic <input checked="" type="checkbox"/> Crawlspace <input type="checkbox"/> Basement	<input type="checkbox"/> Windows/window frames <input type="checkbox"/> Wall surfaces <input checked="" type="checkbox"/> Ceiling surfaces / skylights
SEVERITY	<input type="checkbox"/> None/not applicable	<input type="checkbox"/> Low	<input type="checkbox"/> Medium <input checked="" type="checkbox"/> High
POSSIBLE SOURCE	<input type="checkbox"/> Unable to determine <input type="checkbox"/> N/A	<input checked="" type="checkbox"/> Attic/roof <input type="checkbox"/> Kitchen <input type="checkbox"/> Bathrooms	<input checked="" type="checkbox"/> Exterior <input checked="" type="checkbox"/> Basement/crawlspace <input type="checkbox"/> Laundry
RECOMMEND	<input type="checkbox"/> No recommendations	<input checked="" type="checkbox"/> Divert site drainage <input checked="" type="checkbox"/> Divert roof drainage <input checked="" type="checkbox"/> Repair plumbing leaks	<input checked="" type="checkbox"/> Reduce source of moisture <input checked="" type="checkbox"/> Increase attic/crawl space ventilation <input checked="" type="checkbox"/> Add/use dehumidistat or interval timer <input checked="" type="checkbox"/> Seal foundation / floor cracks / holes
<input type="checkbox"/> Add moisture barrier in crawl space <input checked="" type="checkbox"/> Add/use kitchen and bathroom exhaust fans <input type="checkbox"/> Disconnect humidifier <input type="checkbox"/> Modify heating system			

see section 6.1, 3.1-3.2, 5.0, 4.7 etc

HEAT RECOVERY VENTILATOR (HRV)	Unit location: _____ Manufacturer: _____ <input type="checkbox"/> N/A Est. age: _____	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> Clean filters <input type="checkbox"/> Service/adjust <input type="checkbox"/> Add Heat Recovery Ventilator (HRV)
DEHUMIDISTAT / INTERVAL TIMER	Fan location: <u>Crawlspace</u> Timer location: _____	<input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/> Dehumidistat not checked for accuracy <input checked="" type="checkbox"/> Install dehumidistat / interval timer

RATING

1) Functional/Satisfactory

2) Minor repairs/Maintenance Required

3) Poor/Unsatisfactory

4.6 FIREPLACE(S)

1 2 3

REF # 2016-102

- ◆ CONCEALED FLUE: Although we attempt to determine the box and flue material, it is beyond the scope of this inspection to fully evaluate the flue installation and condition or its ability to draft and function properly.
- ◆ UNLINED FLUE is not safe for regular wood burning use.
- ◆ Wood burning inserts - cannot confirm positive connection to a metal flue liner
- ◆ Cannot confirm proper clearances have been observed

LOCATION # 1 <input type="checkbox"/> Masonry <input type="checkbox"/> Metal system <input type="checkbox"/> FALSE <input type="checkbox"/> Lined box <input type="checkbox"/> Lined flue <input type="checkbox"/> Unlined flue <input type="checkbox"/> Clean flue annually	<input type="checkbox"/> Electric <input type="checkbox"/> GAS <input type="checkbox"/> Direct vent <input type="checkbox"/> Gas log set in masonry fireplace <input type="checkbox"/> WOOD <input type="checkbox"/> With damper <input type="checkbox"/> With wood burning insert Brand _____ BTU input _____ <input type="checkbox"/> CSA certified	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Gas not turned on/pilot not lit <input type="checkbox"/> Have vendor demonstrate fireplace controls <input type="checkbox"/> Have gas fireplace checked by gas company <input type="checkbox"/> Damper fixed open <input type="checkbox"/> Secure damper in open position before use <input type="checkbox"/> Evidence of backdrafting <input type="checkbox"/> Install metal liner in masonry chimney <input type="checkbox"/> Repair/replace gas shut-off <input type="checkbox"/> Possibly not CSA certified
--	--	--

- | | |
|---|--|
| <input type="checkbox"/> Cracked firebricks/missing grout - unsafe - repoint/repair before use
<input type="checkbox"/> Seal gaps between masonry and metal firebox with non-combustible insulation
<input type="checkbox"/> Smoke staining above fireplace opening - may indicate poor draw
<input type="checkbox"/> Flue inspection & cleaning by WETT certified technician is advised now | <input type="checkbox"/> Damper needs repair
<input type="checkbox"/> Efflorescence in firebox
<input type="checkbox"/> Combustion air supply not visible / none |
|---|--|

LOCATION # 2 <input type="checkbox"/> Masonry <input type="checkbox"/> Metal system <input type="checkbox"/> FALSE <input type="checkbox"/> Lined box <input type="checkbox"/> Lined flue <input type="checkbox"/> Unlined flue <input type="checkbox"/> Clean flue annually	<input type="checkbox"/> Electric <input type="checkbox"/> GAS <input type="checkbox"/> Direct vent <input type="checkbox"/> Gas log set in masonry fireplace <input type="checkbox"/> WOOD <input type="checkbox"/> With damper <input type="checkbox"/> With wood burning insert Brand _____ BTU input _____ <input type="checkbox"/> CSA certified	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Gas not turned on/pilot not lit <input type="checkbox"/> Have vendor demonstrate fireplace controls <input type="checkbox"/> Have gas fireplace checked by gas company <input type="checkbox"/> Damper fixed open <input type="checkbox"/> Secure damper in open position before use <input type="checkbox"/> Evidence of backdrafting <input type="checkbox"/> Install metal liner in masonry chimney <input type="checkbox"/> Repair/replace gas shut-off <input type="checkbox"/> Possibly not CSA certified
--	--	--

- | | |
|---|--|
| <input type="checkbox"/> Cracked firebricks/missing grout - unsafe - repoint/repair before use
<input type="checkbox"/> Seal gaps between masonry and metal firebox with non-combustible insulation
<input type="checkbox"/> Smoke staining above fireplace opening - may indicate poor draw
<input type="checkbox"/> Flue inspection & cleaning by WETT certified technician is advised now | <input type="checkbox"/> Damper needs repair
<input type="checkbox"/> Efflorescence in firebox
<input type="checkbox"/> Combustion air supply not visible / none |
|---|--|

LOCATION # 3 <input type="checkbox"/> Masonry <input type="checkbox"/> Metal system <input type="checkbox"/> FALSE <input type="checkbox"/> Lined box <input type="checkbox"/> Lined flue <input type="checkbox"/> Unlined flue <input type="checkbox"/> Clean flue annually	<input type="checkbox"/> Electric <input type="checkbox"/> GAS <input type="checkbox"/> Direct vent <input type="checkbox"/> Gas log set in masonry fireplace <input type="checkbox"/> WOOD <input type="checkbox"/> With damper <input type="checkbox"/> With wood burning insert Brand _____ BTU input _____ <input type="checkbox"/> CSA certified	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Gas not turned on/pilot not lit <input type="checkbox"/> Have vendor demonstrate fireplace controls <input type="checkbox"/> Have gas fireplace checked by gas company <input type="checkbox"/> Damper fixed open <input type="checkbox"/> Secure damper in open position before use <input type="checkbox"/> Evidence of backdrafting <input type="checkbox"/> Install metal liner in masonry chimney <input type="checkbox"/> Repair/replace gas shut-off <input type="checkbox"/> Possibly not CSA certified
--	--	--

- | | |
|---|--|
| <input type="checkbox"/> Cracked firebricks/missing grout - unsafe - repoint/repair before use
<input type="checkbox"/> Seal gaps between masonry and metal firebox with non-combustible insulation
<input type="checkbox"/> Smoke staining above fireplace opening - may indicate poor draw
<input type="checkbox"/> Flue inspection & cleaning by WETT certified technician is advised now | <input type="checkbox"/> Damper needs repair
<input type="checkbox"/> Efflorescence in firebox
<input type="checkbox"/> Combustion air supply not visible / none |
|---|--|

WOOD STOVE Brand _____ Inspection label _____ <input type="checkbox"/> Free standing <input type="checkbox"/> Clean flue and smoke pipe annually	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> Certification label not visible/legible <input type="checkbox"/> Have inspected by WETT technician <input type="checkbox"/> Installation does not meet Cert. specs. <input type="checkbox"/> Hearth too small / inadequate
---	--

- ☐ Combustion air supply - ☐ None ☐ Not visible - Install dedicated combustion air from exterior to the stove.

4.7 BASEMENT & CRAWL SPACE

1 2 3

REF # 2016-108

CONFIGURATION

- ☐ Slab-on-grade
☒ Crawl space

- ☐ Basement:
☐ Full
☐ Partial
☐ Underground garage
- ☐ Finished
☐ Partially finished
☒ Unfinished
☐ Suite
☐ Low ceilings

- ☒ Inaccessible areas, not inspected *West South areas*
☐ Portions of walls/floor not visible due to stored items/cabinets
☐ Area finished, structural elements cannot be fully evaluated
☒ Professional/amateur workmanship *of C.S.*
☐ Past/recent repairs/paint/waterproofing
☐ U/G garage extends beyond building to below patios/landscaping

CRAWL SPACE ACCESS

☐ N/A

- ☒ No access
☐ Stairs
☐ Garage hatch

- ☒ Interior floor hatch
☐ Interior wall hatch
☐ Exterior hatch

- ☒ Traverse of crawl space
☐ Viewed only at opening
☒ Crawl space too low - not accessible
☒ Full evaluation not possible due to stored items/debris

FLOOR

- ☐ BASEMENT:
☐ Concrete floor
☐ Earth floor
☐ Wood subfloor
☐ Carpet/vinyl over concrete - visibility limited

- ☒ CRAWL SPACE:
☐ Concrete floor
☒ Earth floor
☐ With moisture barrier

- ☐ ☐ ☒ Uneven/sloped surface *see sec 5.0*
☐ Routine shrinkage cracks
☐ Add moisture barrier
☒ Worn/stained/damaged flooring
☒ Standing water visible
☐ Past/recent repairs/paint/waterproofing

☒ Possible hidden damage or moisture under wood sub-floor *Floor*

☒ RADON: The presence of radon is undetermined and beyond the scope of this inspection. See Health Canada's website for more information at www.hc-sc.gc.ca and consider using a long term radon testing device to determine radon levels

INSULATION

- ☐ Rigid foam
☒ Fibreglass batts
☐ Spray on
☐ None / Not visible

- ☐ Fallen/damaged - Resecure/replace
☐ Insulate heating ducts/pipes
☐ Plumbing pipes on wrong side of insulation and subject to freezing

- ☐ ☒ ☒ Add insulation between floor joists or to walls to 18" below grade *rim joint only*
☐ Protect exposed foam insulation from fire/cover with gypsum board
☐ Insulation installed on wall / floor joists / rim joists - limited visibility

VAPOUR BARRIER

☐ None / Not visible

- ☐ Poly / paper

- ☐ ☒ ☐ Incomplete / missing vapour barrier
☐ Protect barrier from mechanical damage

VENTILATION

- ☐ U/G garage power ventilator not tested

- ☐ N/A
☐ None

- ☐ Screened vents
☐ Crawl space heated

- ☐ ☒ ☒ Vent screen blocked / damaged / missing
☐ Add foundation vents/heating for ventilation
☒ Keep vents open in summer / closed in winter

DAMAGE/MOISTURE EVIDENCE

☐ None observed

- ☒ Damage visible
☐ Walls
☐ Ceilings
☒ Floors

- ☒ Evidence of moisture seepage
☒ Efflorescence
☒ Damp/wet
☒ Standing water
☒ Stains/mould
☒ Rot damage
☒ Odours
☒ Peeling paint/swollen components

- ☒ Possible insect/rodent infestation/damage: consult exterminator
☒ Evidence of past flooding
☐ Past/recent repairs/paint/waterproofing
☐ Possible membrane failure over ceiling slab—EXTENSIVE REPAIRS MAY BE REQUIRED.

- Review Property Condition Disclosure Statement (PCDS) and ask vendors for history of any flooding or insect/rodent infestation
- Expect seasonal / ongoing dampness / moisture - to help control, refer to section 4.5

RATING

1) Functional/Satisfactory

2) Minor repairs/Maintenance Required

3) Poor/Unsatisfactory

5.0 STRUCTURE

1 2 3

REF # 2016-101

PERIMETER FOUNDATION

- ☐ Slab-on-grade
- ☒ Crawlspace
- ☐ Full Basement
- ☐ Partial Basement
- ☐ Combination
- ☐ Underground garage

FOUNDATION MATERIAL

- ☒ Poured concrete
- ☐ Concrete block
- ☒ Preserved wood
- ☐ Stone
- ☒ Past/recent repairs evident

VISIBILITY

- ☐ Not visible
- ☒ Partially visible
- ☐ Exterior only
- ☐ Interior only
- ☒ Soil too high at foundation - visibility limited

☐ ☒ ☒
North/East Foundation Performing as intended

- ☐ Hairline / moderate/ excessive cracking
- ☒ Differential movement
- ☒ Leaning/bulging
- ☐ Settled/heaved
- ☐ Spalling/deteriorated
- ☐ Exposed/rusted rebar
- ☒ Cold pours/porous wall
- ☐ Form boards/ties left in place
- ☐ No damp-proofing/parging

FOOTINGS

- ☐ None
- ☐ Not visible
- ☐ Partially visible

- ☐ Pier footings
- ☐ Pad footings
- ☐ Spread footings

☐ ☒ ☒

- ☒ Settled/undercut - Northside Footing
- ☐ Possible lowered floor (dug out) - Sand
- ☐ Tree roots possibly affecting structure

☒ Excessive/moderate cracks indicate a past and possible active foundation movement; should be monitored and may require structural repairs or reinforcement. *midsection footing*

☐ Cracks observed - possible source of water penetration

☒ Possible drainage problem - consult drainage expert.

☒ Further evaluation recommended - consult structural engineer.

☐ Mobile home ☐ With tie downs ☐ Add tie downs

Assessing the structural adequacy of apartment buildings is beyond the scope of this visual inspection. For a full evaluation, consult structural engineer. Review Strata Corporation Minutes for references to past and/or future repairs. Obtain copies of any engineering reports.

☐ Adjustment required to cribbing for mobile home. Periodic adjustments are required as seasonal settlement/heaving happens.

No Footings -> base Footing detail @ substructure of Grade Beams
PTW Foundation Possible major replacement
South to S/W side of Building structure -> PTW Foundation
Rot noted @ open of crawlspace vent -> 25 yrs life

SILL PLATE AND FOUNDATION BOLTS

- ☐ Not visible
- ☐ Partially visible

☐ ☒ ☐

- ☒ Sills below grade-possible rot damage
- ☐ Few/many missing or loose nuts
- ☐ Sills not anchored

N/E corner -> sill/rim joist -> partial dry rot -> minor repairs

EXTERIOR WALL CONSTRUCTION

(see section 2.1 - Ext. Walls)

- ☒ Structural components partially/not visible
- ☒ Past/recent repairs evident

- ☒ Wood frame
- ☒ Platform
- ☐ Post & beam
- ☐ Balloon

- ☐ Brick veneer
- ☐ Masonry
- ☐ Stone
- ☐ Log
- ☐ Concrete

☐ ☒ ☒

- ☒ Earth-wood/concrete contact @ North wall and East wall West wall
- ☒ Rot/insect damage
- ☐ Porch beam sagging/rot damage
- ☐ Leaning/bulging/settling
- ☐ Rusting/expanding lintels
- ☐ Posts/logs checking
- ☐ Masonry/mortar/concrete cracks

INTERIOR SUPPORT STRUCTURE

- ☒ Structural components partially/not visible

- ☒ Posts/columns
- ☒ Beams
- ☐ Partition wall

- ☒ Wood
- ☒ Concrete
- ☐ Steel
- ☐ Masonry

☐ ☒ ☒

- ☐ Beam/joist/post cut/cracked/checked
- ☒ Rot/insect damage
- ☐ Temporary jack posts
- ☒ Repair/replace/add support
- ☒ Deteriorated supports/columns

FLOOR CONSTRUCTION

- ☒ Structural components partially/net visible

- ☒ Wood joists
- ☐ Manufactured joists
- ☒ Beams
- ☐ Cross bridging/blocking/bracing

SUBFLOOR

- ☐ Plywood
- ☐ Particle board
- ☐ OSB
- ☒ Boards -> Rotted @ East side
- ☐ Concrete

☐ ☒ ☒

- ☒ Rot/insect damage
- ☐ Excessive squeaking
- ☐ Cantilevers overspanned/damaged
- ☐ Concrete cracked/settled/heaved
- ☐ Concrete broken up/suspended
- ☐ Subfloor poorly secured/edges unsupported
- ☐ Bracing poorly secured/missing/overspanned
- ☐ Floor sagging/deflecting/overspanned

CEILINGS

(see section 3.2: Attic)

- ☒ Structural components partially/not visible

- ☒ Joists
- ☐ Trusses
- ☒ Rafters
- ☐ Concrete

- ☒ Flat
- ☒ Vaulted

☐ ☒ ☐

- ☒ Sagging see attic
- ☒ Large, unusual cracks Roof structure
- ☐ Condensation/staining on interior finishes
- ☐ Truss damage / modification - (see below)

- ☐ Light framing - undersized framing members may allow floors to sag, roofs to droop, etc. Evaluation by a structural engineer is recommended.
- ☐ Improper notching/drilling of joists, beams, posts - reinforcement required.
- ☐ Although structural components were mostly not visible, no signs of major structural defects were observed.

metal structural support @ Westside left cut? see structural engineer

6.1 WATER SUPPLY / DWV

1 2 3

REF # 2016-102

WATER SOURCE

- ☐ Public ☐ Stop not visible
☐ Water stop box located @ _____ ☐ Locate stop box - Contact local Municipality Water Department
☒ Private / Community well - not inspected. Check with local health unit and/or obtain a private contractor review. Have a full potability water test performed by authorized laboratory.

SEWAGE DISPOSAL

- ☐ Public
☒ Private septic system - not inspected. Check with local health unit and/or obtain a private contractor review.

HOSE BIB(S)

- ☐ Tested/not tested
☐ Drained/winterized - not tested

- ☐ Exterior
☐ Garage

☐ ☐ ☒

- ☒ Hose bib not frost protected - winterize
☐ No anti-siphon valves - install
☐ Handle missing/broken/leaking

MAIN WATER SERVICE & SHUT OFF

- Location N, C.S. - North Wall
☐ Undetermined/not observed - request location from vendor

- ☐ Copper
☐ Plastic
☒ Galvanized steel
☐ EPDM
☐ Lead

☐ ☐ ☒

- Estimated diameter: 3/4"
☒ Replace old galvanized/lead service pipe
☐ Shut-off valve stuck/leaking
☐ No pressure reducing valve (PRV) - ADD
☐ With PRV - allows adjustment if necessary

INTERIOR SUPPLY PIPING

- ♦ Piping partially hidden - thorough review not possible
 ♦ Some Polybutylene plastic piping systems have been documented to have defects. Contact qualified expert.

- ☒ Copper
☐ Plastic
☐ Galvanized steel
☐ PolyB with copper/acetyl fittings

☒ ☐ ☐

- ☐ Corrosion on some pipe joints
☐ Hot/cold taps reversed
☐ Water hammer/noise in pipes
☐ Improve supply line support
☐ Incompatible pipe hangers used - replace
☐ Leaks

FLOW RATE

- ♦ Pressure not checked

☒ ☒ ☐

- ☐ Pressure flow too high / too low
☒ Flow rate slow when using multiple fixtures
☐ Add/adjust pressure reducing valve (PRV)

FIXTURE STOPS

- ☐ None ☐ Not tested
☐ Some

☒ ☐ ☐

- ☐ Some valves stuck - need "freeing"
☐ Minor valve leaks

- ☐ Supply piping on wrong side of insulation and is subject to freezing
☐ Install pressure-balanced faucets (see below)

- ☐ Copper/galvanized contact - dielectric fittings required
☐ Cross-connection(s) @ _____

- ♦ Determining the condition of underground main water service piping, drain and sewer pipes is beyond the scope of this inspection
 ♦ Piping partially hidden - thorough review not possible
 ♦ Pressure-balanced faucets ensure water temperature does not fluctuate when multiple fixtures are used (scald prevention)
 ♦ Galvanized / Poly B water piping: some insurance companies may not insure homes with this type of piping.

INTERIOR DRAIN PIPING

- ♦ Piping partially hidden - thorough review not possible
☐ Sewage ejection pump: Location _____
☐ Tested/not tested

- ☒ Plastic
☒ Copper/chrome
☐ Cast iron
☐ Galvanized
☐ Lead

☒ ☐ ☐

- ☐ Corrosion on some pipe joints
☐ Clogged/slow draining fixtures
☐ Improve drain line support/slope (see below)
☐ Improper trap/drain connection
☐ Leaks

WASTE CLEAN-OUT

- ☐ Stack
☐ Floor
☐ Exterior
☐ Concealed/not observed - request location from vendor

- ☒ Plastic
☒ Cast iron
☐ Galvanized steel

☒ ☐ ☐

- ☐ Provide access to or add accessible clean-out
☐ Missing clean-out cap
☐ Basement bathroom fixture drains possibly connected at main waste clean-out

VENTING OF FIXTURES AND STACKS

- ☐ "S" traps in use - consider adding Air Admittance Valve
☐ Auto-vents in use - replace occasionally with Air Admittance Valve

☐ ☒ ☐

- ♦ Unable to fully view vent pipes
☐ Vent stack terminates improperly
☐ Possible un-vented fixture(s): _____

- ☒ Plumbing repairs / upgrades done in a professional / amateur workmanship
☐ Drain pipe slope too steep - may result in clogging
☐ DWV pipes exposed on outside of walls are subject to freezing
☐ **CONDOMINIUM INSPECTION:** Evaluation of piping outside subject unit is beyond the scope of this inspection. Refer to Strata Council Minutes for repair, replacement, and maintenance information
recommend additional vent @ kitchen sink - East

6.1 WATER SUPPLY / DWV (cont.)		1	2	3	REF # <u>2016-102</u>	
FLOOR DRAIN(S) <input type="checkbox"/> None <input type="checkbox"/> Not visible <input checked="" type="checkbox"/> Proper drainage cannot be confirmed	Location: <input type="checkbox"/> Basement <input type="checkbox"/> HWT overflow pan <input type="checkbox"/> Mechanical room <input type="checkbox"/> Laundry room <input type="checkbox"/> Exterior stair wells <input type="checkbox"/> Catch basin	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Blocked <input type="checkbox"/> Missing/damaged grate <input type="checkbox"/> Flush with hose to check <input type="checkbox"/> Install backflow preventer <input type="checkbox"/> Installation of floor drain is recommended <input type="checkbox"/> Ensure water in all traps to provide seal <input type="checkbox"/> Catch basin/drain should be cleaned	
SUMP <input type="checkbox"/> None/not visible <input type="checkbox"/> Pump not tested	<input type="checkbox"/> Interior <input type="checkbox"/> Exterior <input type="checkbox"/> Concrete cover not removed <input type="checkbox"/> With pump <input type="checkbox"/> With drain tile <input type="checkbox"/> No tile	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Water in pit <input checked="" type="checkbox"/> Add sump pump <input type="checkbox"/> Improperly drained to sanitary sewer <input type="checkbox"/> Install back flow preventer/check valve	
MISCELLANEOUS <input type="checkbox"/> Fire sprinkler system <input type="checkbox"/> Lawn sprinkler system <input type="checkbox"/> Water softener <input type="checkbox"/> Water filter <input type="checkbox"/> Wet bar <input type="checkbox"/> Fire/lawn sprinkler systems, water softeners/filters are beyond the scope of this inspection. <input checked="" type="checkbox"/> Fire sprinkler systems must be tested annually by fire suppression technicians. <input checked="" type="checkbox"/> Have vendor demonstrate operation of lawn sprinkler system.						
<p style="text-align: center;"><i>Crawlspace → wet → recommend 2-3 sump pumps to control ground water issue.</i></p>						
6.2 HOT WATER SUPPLY		LOCATION <u>Kitchen</u>				
TYPE	<input checked="" type="checkbox"/> Directly fired <input type="checkbox"/> Indirectly fired <input type="checkbox"/> Tankless coil	<input type="checkbox"/> Natural gas <input checked="" type="checkbox"/> Electric <i>on demand</i>	<input type="checkbox"/> Propane <input type="checkbox"/> Oil <input type="checkbox"/> Solar	<input checked="" type="checkbox"/> GAS/OIL: normal service life 7 - 10 years <input checked="" type="checkbox"/> ELECTRIC: normal service life 9 - 12 years		
WATER HEATER <input type="checkbox"/> With overflow pan <input type="checkbox"/> With drain <input type="checkbox"/> With seismic/safety strap <input type="checkbox"/> With insulation blanket	Manufacturer: <u>Ariston</u> Est. age: <u>2008</u> Est. capacity: _____ <input type="checkbox"/> Label missing/inaccessible - data not observed <input type="checkbox"/> Unit not accessible	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Tank rusted/damaged/scorched/leaking <input type="checkbox"/> Water lines/fittings rusted/leaking <input type="checkbox"/> Reversed water line connections <input type="checkbox"/> Install overflow pan & drain <input type="checkbox"/> Temperature set too high/too low <input type="checkbox"/> Install seismic supports	
BURNERS AND CONTROL (gas/oil) <input checked="" type="checkbox"/> Not tested		<input type="checkbox"/> Pilot not lit/gas turned off	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> Excessive rust flakes in burner chamber <input type="checkbox"/> Scorch marks at flame-shield <input type="checkbox"/> Flame-shield missing
FLUE (gas/oil) <input type="checkbox"/> Direct vent <input type="checkbox"/> Dedicated vent <input type="checkbox"/> Common with furnace		<input type="checkbox"/> Draft diverter hood (gas) <input type="checkbox"/> Forced draft <input type="checkbox"/> Damper <input type="checkbox"/> Barometric draft regulator (oil only) <input type="checkbox"/> Flue connected to masonry chimney	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Replace/install draft diverter hood <input type="checkbox"/> Loose/improper connections <input type="checkbox"/> Evidence of flue gas spillage/backdrafting <input type="checkbox"/> Improper clearances/slope/size/support <input type="checkbox"/> Insufficient combustion air supply
VALVES		<input checked="" type="checkbox"/> Temperature/pressure relief valve (TP) <input type="checkbox"/> Vacuum breaker <input checked="" type="checkbox"/> Water shut off valve <input type="checkbox"/> Gas valve	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Missing/broken/leaky TP valve <input type="checkbox"/> Overflow pipe missing/short/slopes upward <input type="checkbox"/> Add/replace overflow pipe / vacuum breaker <input type="checkbox"/> Install water shut off valve <input type="checkbox"/> Leaks
ELEMENTS/BREAKERS (electric only) Top element <u>1500</u> <u>Watts</u> Lower element _____ <u>Watts</u>		<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Add mechanical coupler to breakers
<input type="checkbox"/> Water heater appears to be at or near the end of its service life—failure probability is high - budget for replacement. <input type="checkbox"/> TP valve located on the cold-water inlet pipe - POTENTIAL HAZARD <input type="checkbox"/> Water heater BTU input exceeds TP valve BTU rating - POTENTIAL HAZARD <input type="checkbox"/> CONDOMINIUM INSPECTION: Commercial boilers & tanks are beyond the scope of this inspection. Refer to Strata Council minutes for repair, replacement, and maintenance information.						

7.0 ELECTRICAL SYSTEM

1 2 3

REF # 2016-102

ELECTRIC SERVICE

- ☒ Overhead ☐ 120 Volt system ☒ Single Phase
☐ Underground (Exterior service wire connection not visible) ☒ 120/240 Volt system ☐ Three Phase
☐ 120/208 Volt system

☒ ☐ ☐

- ☐ Service cable deteriorated
☐ Drip loop damaged - repair
☐ Poorly attached wires at masthead/roof
☐ Insufficient clearance - SAFETY HAZARD
☐ 60/100 amp. meter base outdated
☐ Provide weatherproof protection for meter
☐ CONTACT PROPER AUTHORITY

panel cover missing screws - installation of screws recommended

MAIN PANEL LOCATED Storage room

- ☒ Power On
☐ Power OFF: Client advised to arrange to have system activated and to have system inspected before subject removal date.

- ☐ Main panel cover could not be removed
 Restricted access due to:

- ☐ Panel slots full
☒ Room for expansion # 2 single pole breaker

◆ All branch circuits should be identified on main panel board legend

◆ Maintain clearance of 40 inches in front of panel for access

SERVICE CABLE

- ☒ Copper ☐ Not visible
☐ Aluminum
☐ Copper clad

Rating 200 amps

☒ ☐ ☐

- ☐ Improper service (undersized)
☐ Improper splices
☐ Apply anti-oxidant paste to aluminum wire connections

MAIN GROUNDING

- ☒ Copper ☐ Ground rod(s)
☐ Aluminum ☐ Plumbing ground
☒ Copper clad ☐ Gas line connection

☒ Panel connection

☐ ☐ ☐

- ☒ Partly/not visible
☐ Tighten/replace clamp
☐ Inadequate/improper ground
☐ Plumbing/gas line should be bonded to ground

MAIN DISCONNECT

- ☒ Breakers ☐ Located in electrical room (strata units)
☐ Glass fuses ☐ No access - not observed
☐ Cartridge fuses

Rating 200 amps

☒ ☐ ☐

- ☐ No main disconnect at panel - add for safety
☐ Breaker/fuse amperage exceeds wire capacity
☐ Main cables double lugged/tapped; circuit unprotected

- ☒ Evidence of electrical additions/upgrades. Cannot confirm compliance with current standards; system should be evaluated by an electrical contractor.
☐ 60 AMP SERVICE: although this system may be adequate for the existing connected electrical load, some insurance companies may not insure a house with less than 100 amp service. Consult electrical contractor and upgrade as required.

240 volt breakers 2 pole tripped
 < see electrician possible

SERVICE PANEL

- ☒ Breakers ☐ Add knock-out covers to protect openings
☐ Glass fuses ☐ Install AFCI's at bedroom circuits (see below)
☐ Cartridge fuses ☐ GFCI breaker
☐ Arc-fault circuit interrupters (AFCI)

Max Rating 200 amps

☐ ☒ ☐

- ☐ Panel undersized/damaged/rusted/scorched
☐ Breaker/fuse amperage exceeds wire capacity
☐ Replace breaker/fuse which is oversized for wire
☒ Breaker/fuse double lugged; condition not hazardous but may result in nuisance tripping
☐ 240V breaker(s) require couplers on toggles

CIRCUIT WIRING

- ☒ Copper ☒ Knob & tube
☐ Aluminum ☒ NM sheathing
☐ Copper clad ☒ Armoured cable

☒ Grounded
☐ Ungrounded

☒ ☐ ☐

- ☐ Abandoned wire(s) in panel
☐ Damaged/frayed/overheated wiring
☐ Circuit ground wires connected to neutral bus
☐ Fused neutrals

appears disconnected

- ◆ Recent changes to standards require that at a minimum, AFCI's should be installed in the service panel to protect circuits serving bedrooms in dwelling units to help prevent fires caused by arcing due to breaks in electrical wire insulation.
☐ Protect exposed surface wiring located at _____
☐ Attic insulation covering knob & tube wiring - POTENTIAL FIRE HAZARD.
☐ PLEASE NOTE: Knob & tube / aluminum wiring: some insurance companies may not insure homes with this type of wiring.
☐ Aluminum wiring: old devices/connectors, condition can be hazardous. Improve to new safer CO/ALR devices or "pig-tail" existing devices/connectors.
☐ DECOR outlets and switches are not compatible or rated for aluminum wiring. Consult electrical contractor.
☐ Apply anti-oxidant paste to aluminum wire connections at distribution panel.
☐ Armoured cable required for: furnace/hot water tank/garbage disposal/surface wiring.
☐ Open junction box(es) or improper splicing.

◆ ALL RECOMMENDED CORRECTIONS SHOULD BE PERFORMED BY AN ELECTRICAL CONTRACTOR IN ACCORDANCE WITH CURRENT STANDARDS.

RATING

1) Functional/Satisfactory

2) Minor repairs/Maintenance Required

3) Poor/Unsatisfactory

7.0 ELECTRICAL SYSTEM (cont.)

1 2 3

REF # 2016-102

☒ Sample of switches and outlets tested appear serviceable

☒ Occupants belongings prevent testing of some outlets & switches

AREA LIGHTING

☒ 3-way switches, hall and stairs ☐ Exterior lights

☒ ☐ ☐

☐ Lights/switches not functional
☐ Closet light is hazardous/subject to damage
☐ Recessed lights may not be approved for installation in contact with attic insulation

CEILING FAN

Location: X2

☒ With lights

☒ ☐ ☐

☐ ☐ ☐

☐ ☐ ☐

☐ Excessive vibration
☐ Noisy
☐ Not functional

GROUNDING PLUG OUTLETS

☒ Entire house
☐ Kitchen
☐ Bathroom(s)
☐ Laundry
☐ Exterior

Plug outlets with:
☐ Open ground
☐ Open neutral
☐ Open hot
☐ Reversed polarity

☒ ☒ ☐

☒ Add extra room outlets
☐ Outlet(s) not functional
☐ Improve to grounded outlets
☐ Portion only - balance 2 prong/ungrounded
☒ Provide weatherproof protection (exterior)

GROUND FAULT PROTECTION

☐ Bathroom(s)
☐ Laundry
☐ Kitchen
☐ Exterior

☐ Garage
☐ Pool
☐ Hot tub
☐ Whirlpool

☐ ☒ ☒

none

☐ Breaker/outlet not functional
☐ GFCI failed @
☐ Razor outlet(s) - Replace with (GFCI outlet(s))

◆ Ground Fault Circuit Interrupters (GFCI) at outlets in bathroom/laundry/kitchen/exterior are an effective protection against electrical shock.

☒ Add GFCI outlet(s) @ Bathrooms, Kitchen, exterior outlets

☐ Remove "permanent" extension cords (POTENTIAL FIRE HAZARD)

☐ Broken, worn or missing outlet receptacles, cover plates or switches - replace where necessary

ALARM SYSTEMS

Smoke alarm(s)

☐ Heat detectors

◆ Not tested

☐ None
☐ Electric
☐ Battery

☐ CO monitor
☐ Security system
☐ Water alarm

☒ Plan to add: Hardwire smoke detectors
☐ Install CO monitor
◆ Always assure batteries charged by testing
◆ Smoke alarms should be present in all required areas Loft

DOORBELL

☐ None/not tested

☐ Intercom/video

☐ ☐ ☐

☐ Not functional

SUB-PANEL #1

LOCATION mezzanine

FEED CABLE

☐ Copper
☒ Aluminum
☐ Copper clad

☐ PVC conduit
☐ Rigid metal conduit
☒ Teck cable

☒ ☐ ☐

☐ Improper service (undersized)
☐ Improper splices
☐ Apply anti-oxidant paste to aluminum wire connections

GROUNDING

☒ Copper
☐ Aluminum
☐ Copper clad

☒ Panel connection

☒ ☐ ☐

☐ Improper ground, see previous page
☐ Ground bus bar bonded to neutral bus bar
☐ Inadequate/improper ground

MAIN DISCONNECT

☒ Breakers

☐ Glass fuses
☐ Cartridge fuses

☒ ☐ ☐

☐ Breaker/fuse amperage exceeds wire capacity
☐ Main cables double lugged/tapped; circuit unprotected

DISTRIBUTION PANEL

Maximum Panel Rating
125 Amps

☒ Breakers
☐ Glass/cartridge fuses

☒ ☐ ☐

☐ Breaker/fuse amperage exceeds wire capacity
☐ Breaker/fuse double lugged; condition not hazardous but may result in nuisance tripping

CIRCUIT WIRING

☒ Copper
☐ Aluminum
☐ Copper clad

☐ Knob & Tube
☒ NM Sheathing
☒ Armoured cable

☒ ☐ ☐

☐ Pigtail required - see previous page
☐ Abandoned wire(s) in panel
☐ Circuit ground wires connected to neutral bus

8.0 HEATING/COOLING SYSTEMS

1 2 3

REF # 2016-102

FORCED AIR FURNACE

FUEL SOURCE ☐ Gas ☐ Electric ☐ Oil FURNACE TYPE ☐ Upflow ☐ Downflow ☐ Horiz. flow BREAKERS (Electric furnace only):

GAS LINES ☐ N/A ☐ Black iron ☐ POSSIBLE GAS LEAK: CONTACT GAS COMPANY
☐ Gas shut off ☐ Non-soldered copper ☐ Improper/non traditional gas line

♦ FOR SAFETY: Maintain minimum 12" clearance around heating equipment as per manufacturer's specifications.

FURNACE EXTERIOR Manufacturer: ☐ ☐ ☐ Est. age: ☐ ☐ ☐ Est. capacity: ☐ BTU output ☐ Exterior casing rusted/damaged
☐ Score marks visible
♦ Keep area around furnace clean

BURNERS/HEAT EXCHANGERS ♦ Heat exchanger cannot be fully viewed ☐ ☐ ☐ ♦ Electric heating elements not visible ☐ ☐ ☐ ☐ Excessive rust/dirt
☐ Clean, service and adjust
☐ Heat exchanger cracked - replace furnace

IGNITION ☐ Standing pilot light ☐ Electronic ☐ ☐ ☐ ☐ Unstable or dancing flame

CONTROLS ☐ Limit control ☐ Thermostat ☐ ☐ ☐ ☐ ♦ Thermostat not checked for accuracy ☐ Interval timer ☐ Humidistat ☐ ☐ ☐ ☐ Primary control (oil only)
☐ Thermostat(s) loose - secure to wall
☐ Gas shut off - Furnace not tested

VALVES ☐ Main gas valve ☐ ☐ ☐ ☐ ☐ ☐ Gas pressure regulator

EXPOSED FLUE ☐ Metal ☐ Forced draft (high efficiency) ☐ ☐ ☐ ☐ Flue pipe too close to combustible surfaces; needs protection. ☐ Plastic ☐ Barometric draft regulator (oil only) ☐ ☐ ☐ Improper drafting
☐ Draft hood ☐ Repair/replace
☐ Slope correction required
☐ See 6.2 Hot Water tank

DISTRIBUTION DUCTS ☐ Steel ☐ ☐ ☐ ☐ ♦ Ductwork partially concealed; thorough review not possible
☐ Possible asbestos materials - should be professionally sealed, encapsulated, or removed. ☐ Aluminum ☐ ☐ ☐ ☐ Leaky joints - seal joints
☐ Flexible ☐ ☐ ☐ ☐ Poor / broken supports

BLOWER MOTOR/FAN ☐ Direct drive ☐ Motor hot ☐ ☐ ☐ ☐ ☐ Belt drive ☐ Replace fan belt ☐ ☐ ☐ ☐ Motor/fan noisy; have checked
☐ Motor/fan needs cleaning
♦ Lubricate blower/circulator motors annually

☐ Humidifiers cannot be confirmed as functional and require regular cleaning and servicing as per manufacturer's specifications.
☐ Use "summer switch" to operate furnace blower to improve heat distribution and ventilation during cold weather

FILTERS ☐ Disposable ☐ Electronic ☐ ☐ ☐ ☐ ☐ Re-usable ☐ Electrostatic ☐ ☐ ☐ ☐ Filter needs cleaning or changing now
☐ Electronic filter turned off / not checked
☐ Bad fit / missing / poor access to filter

♦ Change furnace filters 2 to 4 times per year ☐ Recommend upgrading to pleated filter medium

COMBUSTION AIR SUPPLY ☐ Open duct ☐ ☐ ☐ ☐ ♦ Clean outside combustion air supply grill annually
☐ Connected to return air plenum/ burner chamber ☐ ☐ ☐ ☐ Install combustion air supply duct
☐ Not visible

WARM AIR SUPPLY COLD AIR RETURN REGISTERS ☐ Heat supply missing at: ☐ ☐ ☐ ☐ ☐ Grill missing / broken
☐ Inadequate return air ☐ ☐ ☐ ☐ Undercut doors to room
☐ Poor general air movement throughout house ☐ ☐ ☐ ☐ Air not coming out of every grill
☐ Cannot confirm adequate heating to all rooms ☐ ☐ ☐ ☐ Recommend cleaning interior of ductwork
☐ Appears adequate

☐ Old furnace - should be evaluated by qualified gas fitter
☐ Furnace appears to be at or near the end of its useful life - budget for replacement.
☒ Possible buried oil tank; locate, test for residual oil products & dispose according to applicable requirements of the authority having jurisdiction.

also may have been above grade oil tank
Possible fuel line noted @ exterior wall stucco
see Kootenay Furnace → Slocon Village

RATING

1) Functional/Satisfactory

2) Minor repairs/Maintenance Required

3) Poor/Unsatisfactory

8.0 HEATING/COOLING SYSTEMS**1 2 3**REF # 2016-102**ELECTRIC HEATING SYSTEM**

BREAKER(S)

☒ 2 X 15A # _____
☒ 2 X 20A # _____
☐ _____
☐ 2 X 30A # _____
☐ 1 X 30A # _____
☐ _____☒ ☒ ☐☐ 240 Volt breaker(s) require mechanical couplers on toggles
♦ Refer to Section 7.0 - Electrical System

♦ Unless otherwise specified, 240 Volt breaker(s) are mechanically coupled

→ 240 volt breaker
Tripped @ Panel → unknown
see Electrician

ELECTRIC BASEBOARD TYPE HEATING SYSTEM

THERMOSTATS

☒ Wall mounted ☒ Heater mounted☒ ☐ ☐☐ Cover(s) missing
☐ Thermostat(s) loose - secure to wall
♦ Thermostats are not checked for accuracyBASEBOARD
HEATERS☐ Missing at: _____

_____☐ ☐ ☒☐ Loose - repairs required (see below)
☐ Casing damaged / rusted
☐ Not working - repair or replace (see below)
☐ Potential hazardous conditions (see below)CONVECTION
HEATERS☒ Mounted on wall ☐ With fan
☐ Recessed in wall
☐ Floor insert(s)☐ ☒ ☐☒ Not working - repair or replace (see below)Location: Throughout Intercom2 @ Kitchen?

♦ Baseboard heaters must be kept free from obstruction; flammable materials that rest against, or fall into the heaters can pose a fire hazard. Provide adequate air flow and clearances around the heaters.

☐ Baseboard / convection heaters tested functional at time of inspection

wall convector heaters @ Bathrooms → need
replacement due to age → Possible Fire hazard

PORTABLE
HEATERSLocation: _____
_____☐ ☐ ☐☐ House wiring cannot handle extra load
☐ Damp/wet area noted - **Hazardous Condition**
☐ Remove heater(s)

♦ Auxiliary heating suggests possible inadequate heat supply

ELECTRIC RADIANT HEATING SYSTEM

- ☐ RADIANT CEILING PANEL SYSTEM
☐ RADIANT WALL PANEL SYSTEM
☐ RADIANT FLOOR PANEL SYSTEM

Brand _____

Serial No. _____

☐ Serial No. is not visible

♦ RECALL of Flexwatt Radiant Ceiling Heating Panels, Product No's:

R13C13H120, R13C13H208, R13C13H240 rated 13 Watts per panel
R17C20H120, R17C20H208, R17C20H240 rated 20 Watts per panel
R25C30H120, R25C30H208, R25C30H240 rated 30 Watts per panel

- ♦ Thermostats are not checked for accuracy
♦ Improper installations can pose a fire hazard
☐ Radiant panel system not visible
☐ If one or more panel sets are cold while other panel sets are warm
- power connections might be loose or panels may be defective.
☐ CONTACT ELECTRICAL INSPECTOR ASAP

Additional testing by CSA has determined that in some circumstances these panels may overheat. If any of the listed ceiling heating panels have been identified, contact a qualified electrical contractor as soon as possible for further evaluation.

RATING

1) Functional/Satisfactory

2) Minor repairs/Maintenance Required

3) Poor/Unsatisfactory

9.0 SUMMARY

REF # 2016-102

This summary is intended to provide an overview of the condition of the major systems inspected. The client is encouraged to keep and review the complete report. The client is advised to execute a "pre-closing walkthrough" with the seller.

OBTAIN APPLICABLE PERMITS, RECEIPTS, WARRANTIES AND/OR PRIVATE REPORT(S) FOR:

- Additions/converted spaces
- Sprinkler system
- Alarm system
- Intercom/radio
- Pool/spa & equipment
- Well & water potability
- Septic system
- Underground oil tank
- Insect/rodent infestation
- Underground drain tile cleaning/replacement
- Major appliances
- System upgrades - eg. heating, roof, etc

MAJOR SYSTEMS CONDITION OVERVIEW

1.1 Site Conditions	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input checked="" type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input checked="" type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Contractor</i>
1.2 Garage/Carport	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input type="checkbox"/> FURTHER INVESTIGATION
2.1 Exterior Walls & Accessories	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input checked="" type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input checked="" type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Contractor</i>
2.2 Exterior Doors & Windows	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input checked="" type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input checked="" type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Contractor</i>
2.3 Porches & Decks	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input checked="" type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input checked="" type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Contractor</i>
2.4 Balconies	<input checked="" type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input checked="" type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Contractor</i>
2.5 Solariums, Patios & Elevated Walkways	<input checked="" type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input type="checkbox"/> FURTHER INVESTIGATION
3.1 Roofing	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input checked="" type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input checked="" type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Contractor</i>
3.2 Attic, Ventilation & Insulation	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input checked="" type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input checked="" type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Verminicide</i>
4.1 Interior Walls, Ceilings & Floors	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input checked="" type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Contractor</i>
4.2 Kitchen	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input checked="" type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Contractor</i>
4.3 Bathroom(s)	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input checked="" type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Contractor</i>
4.4 Laundry Facilities	<input checked="" type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input type="checkbox"/> FURTHER INVESTIGATION
4.5 Ventilation & Condensation	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input checked="" type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Contractor</i>
4.6 Fireplace(s)	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input type="checkbox"/> FURTHER INVESTIGATION
4.7 Basement & Crawl Space	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input checked="" type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input checked="" type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Contractor</i>
5.0 Structure	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input checked="" type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input checked="" type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Contractor</i>
6.1 Water Supply & DWV	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input checked="" type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input checked="" type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Contractor</i>
6.2 Hot Water Supply	<input type="checkbox"/> N/A	<input checked="" type="checkbox"/> FUNCTIONAL (no problems seen)	<input type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input type="checkbox"/> FURTHER INVESTIGATION
7.0 Electrical	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input checked="" type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Electrician</i>
8.0 Heating & Cooling	<input type="checkbox"/> N/A	<input type="checkbox"/> FUNCTIONAL (no problems seen)	<input checked="" type="checkbox"/> MINOR REPAIRS / MAINTENANCE <input type="checkbox"/> MAJOR REPAIRS / REPLACEMENT	<input checked="" type="checkbox"/> FURTHER INVESTIGATION <i>Keenan Furnace</i>
GLOBAL RATING	The overall rating for this house, considering its age and construction and comparing it to other similar houses is:			
	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
	BELOW AVERAGE		TYPICAL	ABOVE AVERAGE

MAINTENANCE TIPS

GENERAL

Preventive maintenance can prolong the life of the different components of your home. This chart includes a basic list of maintenance items. Use it only as a guide - repair or look after problems as they arise.

Of course, always use common sense - hairline cracks in concrete or on wall surfaces are seldom indications of serious problems, but a crack which appears suddenly and widens noticeably over a short period of time, or doors which suddenly do not close properly, could be indications of serious structural problems and expert advice is recommended.

Regular maintenance is not for everyone. For some people, hiring a contractor for maintenance inspections and to do repairs may be the best idea.

CAUTION:

- ◆ Note the location of all gas shut-off valves.
- ◆ Learn the location of electric service panels and label each circuit. Always shut off the power before making any repairs to the electrical system and unplug appliances before attempting any cleaning or servicing.
- ◆ Note the location of the water main shut-off valve. It may be necessary to shut off the water to repair plumbing fixtures or to make repairs to some appliances.
- ◆ Refer to manufacturers' manuals before inspecting, cleaning or repairing appliances, particularly heating appliances and furnaces, air conditioning systems or water heaters.

EVERY MONTH

SMOKE ALARM	◆ Test batteries and replace if necessary
FIRE EXTINGUISHER	◆ Verify if fully charged. Recharge if necessary
GROUND FAULT INTERRUPTERS	◆ Exercise to ensure proper function
GARBAGE DISPOSER	◆ Flush with hot water and baking soda
FORCED WARM AIR HEATING SYSTEM	◆ Replace or clean air filter and vacuum registers
STEAM HEATING SYSTEM	◆ Check safety valve and steam pressure gauge and drain expansion tank if necessary; check water level gauge and add water if needed; drain water until clear to eliminate sediment
HOT WATER HEATING SYSTEM	◆ Test relief valve and replace if necessary; check pressure gauge and drain expansion tank if necessary
REFRIGERATED AIR CONDITIONER	◆ Clean or replace filter; clean condenser and evaporator coils and condensate drain
EVAPORATIVE AIR CONDITIONER	◆ Replace blankets; check air flow and clean or repair unit as necessary
HEAT PUMP	◆ Clean or replace air filter; clean condenser, evaporator coils and condensate drain; remove snow and/or debris from outdoor portion of unit

EVERY TWO MONTHS

RANGE HOOD FAN	◆ Clean grease filter
OIL BURNER (PRESSURE TYPE)	◆ Inspect and clean
WALL FURNACE	◆ Clean grills

EVERY THREE MONTHS

FAUCETS	◆ Clean aerators
TUB DRAIN ASSEMBLY	◆ Clean out debris; inspect rubber seal and replace if necessary
FLOOR DRAIN	◆ Clean out debris; flush with clear water
DISHWASHER	◆ Clean stainer, spray arm and air gap

MAINTENANCE TIPS

(Page 2)

EVERY SIX MONTHS

BASEMENT AND FOUNDATION	◆ Check for cracks and moisture; repair if necessary
TOILET	◆ Check for leaks and repair if necessary
GARBAGE DISPOSER	◆ Tighten drain connections and fasteners
CLOTHES WASHER	◆ Clean water inlet filters; check hoses for leaks and replace if necessary
CLOTHES DRYER	◆ Vacuum lint from ducts and surrounding areas
REFRIGERATOR	◆ Clean drain hole and pan; wash door gaskets; vacuum condenser coils
EXHAUST FAN	◆ Clean grill and fan blades
RANGE HOOD FAN	◆ Wash fan blades and housing
ELECTRICAL	◆ Exercise circuit breakers

ANNUALLY

GARAGE DOORS	◆ Clean and lubricate hinges
SEPTIC TANK	◆ Have a professional check the tank (watch for back-up throughout the year)
WATER HEATER	◆ Test temperature-pressure relief valve (PRV) and replace if necessary; clean burner ports (gas heater)
REFRIGERATOR	◆ Test door seal; replace gasket when necessary; check temperature and adjust if necessary
RECIRCULATING RANGE HOOD	◆ Replace charcoal filter pellets

THINGS TO KEEP AN EYE ON

DURING/AFTER WET WEATHER	<ul style="list-style-type: none"> ◆ Check ceilings and surfaces around doors and windows for moisture penetration. ◆ Check for evidence of water penetration in attic and ceilings. ◆ Check basement and crawlspace for moisture or leakage. ◆ Make sure downspouts divert water away from foundation walls.
INTERIOR <ul style="list-style-type: none"> ◆ STAIRS ◆ CEILING AREAS (BELOW KITCHEN & BATHROOM AREAS) ◆ CAULKING 	<ul style="list-style-type: none"> ◆ Check for loose railings and treads. ◆ Check for signs of leakage ◆ Inspect caulking around tubs, showers and sinks. Replace if deteriorating.
ELECTRICAL	<ul style="list-style-type: none"> ◆ Check lamp cords, extensions cords and plugs for damage and wear. Replace as required. ◆ If circuit breakers trip or fuses blow frequently, or an outlet sparks or shorts out, contact a licensed electrician for repairs.

ADDITIONAL COMMENTS (if applicable)

SEASONAL MAINTENANCE TIPS

(Page 3)

SPRING

PLUMBING	<ul style="list-style-type: none"> Flush hot water tank until clear of sediment. Do not close valve while draining, as a heated empty tank is potentially explosive. Inspect flue assembly (if gas-fired). Check lawn sprinkler for leaky valves and exposed lines. Have well water checked for safety.
ROOF	<ul style="list-style-type: none"> Clean build-up of dirt/organic material. Do not powerwash roofs. Check for any missing, loose or damaged shingles. Check for open seams, blisters or bald areas on flat/low slope roofs. Check flashings around all surface projections and sidewalls. Check antenna supports for possible leak source. Check fascia and soffits for deterioration and damage.
GUTTERS AND DOWNSPOUTS	<ul style="list-style-type: none"> Clean gutters; do not flush debris into underground drains. Repair any weaknesses. Check for proper drainage and repair if necessary.
EXTERIOR	
♦ CAULKING	♦ Inspect caulking and replace if necessary.
♦ WINDOW SILLS, DOOR SILLS AND THRESHOLDS	♦ Fill cracks, caulk edges and repaint. Replace if necessary.
♦ WINDOW SCREENS AND SCREEN DOORS	♦ Clean screening; repaint/replace as necessary; tighten or repair loose or damaged frames and repaint if necessary; replace broken, worn or missing hardware; tighten and lubricate door hinges and closures.
INTERIOR	
♦ WHOLE-HOUSE OR ATTIC FAN	♦ Clean unit; check belt tension and adjust if necessary; replace cracked or worn belt; tighten screws and bolts; lubricate motor bearings.
♦ HOT WATER HEATING SYSTEM	♦ Lubricate circulating pump and motor.
♦ EVAPORATIVE AIR CONDITIONER	♦ Clean unit; check belt tension and adjust if necessary; replace cracked or worn belt.
♦ HEAT PUMP	♦ Lubricate blower motor.
♦ REFRIGERATED AIR CONDITIONER	♦ Lubricate blower motor.

AUTUMN

PLUMBING	<ul style="list-style-type: none"> Exercise sump pump to ensure proper operation before fall rains.
ROOF	<ul style="list-style-type: none"> Inspect roof surface, flashing, eaves, and soffits; repair if necessary.
CHIMNEY	<ul style="list-style-type: none"> Clean flue (more frequently if fireplace is used often). Repair any cracks in flue or crumbling mortar.
EXTERIOR	
♦ CAULKING	♦ Inspect and repair where necessary.
♦ STORM WINDOWS AND DOORS	♦ Replace cracked or broken glass; repair and repaint frames if necessary; repair or replace any worn or missing hardware; tighten and lubricate hinges and closures.
♦ SIDING	♦ Clean and inspect; repair if necessary.
♦ LANDSCAPING	♦ Trim shrubs and trees away from roof and exterior walls.
HEATING SYSTEM	
♦ FORCED AIR SYSTEM	♦ Have furnace cleaned and serviced.
♦ GAS BURNER	♦ Clean outside combustion air supply grill.
♦ OIL BURNER	♦ Vacuum heat exchanger surfaces; lubricate blower motor; check fan belt tension and adjust if necessary; replace cracked or worn belt; check for leaks in ducts and repair if necessary.
♦ HOT WATER SYSTEM	♦ Clean burner and ports.
♦ THERMOSTATS	♦ Have professionally serviced.
	♦ Lubricate pump and motor; bleed air from radiators and convectors.
	♦ Clean heat sensor, contact points and contacts; check accuracy and replace if necessary.

WINTER

PLUMBING	<ul style="list-style-type: none"> Shut off and drain exterior pipes and valves before freezing weather.
-----------------	---